



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

No. 2 PANDAN CRESCENT

SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Mdm Tan Peck Lin 222 Westwood Avenue #09-12 Singapore 648355 Mobile: 97508335		
			Document No.				
			0				
			Document Date				
			07/09/2024				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	ZRE210R	GEXGPZ S1	02/03/2020	EY0074X	0	32871	EY0074X
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MR2BE3BE000007236		1ZR0F14609	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY-AI TP INS: TP VEH:SHC625L DATE OF ACC:06.09.2024				50	180.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				200	500.00
3	B	BP-LAB2 REPLACE AND REFOCUS HEADLAMP				134.64	
4	B	BP-LAB2 CONDUCT COMPUTERISED CHASSIS ALIGNMENT				1881.00	
5	S	BP-SUBLET SUPPLY NO PLATE 4				80.00	
6	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00	
7	B	BP-MECH2 TO CONDUCT ADJUSTMENT ON FRONT RADAR SENSOR				198.00	
8	B	BP-MECH2 R/I AC CONDENSOR, PIPING AND REGAS				396.00	
9	B	BP-MECH2 R/I FUSE BOX ASSY TO FAC REPAIR.				792.00	
10	B	BP-MECH2 R/I ABS PUMP, BRAKE SYSTEM TO FAC REPAIR				792.00	
11	B	BP-MECH2 LIFT UP ENGINE TO FAC REPAIR				1584.00	
12	B	BP-MECH2 R/I UNDER CARRIAGE TO FAC REPAIR.				1584.00	
13	B	BP-MECH2 TO CONDUCT FULL WHEEL ALIGNMENT				198.00	
14	B	BP-LAB2 REPLACE ACC DAMAGED PARTS				4752.00	
15	B	BP-RES2 RESPRAY ACC AFFECTED AREAS				3936.00	
16	Z	BP-SUNDRY FOGLAMP CHROME 1				250.00	
For & on behalf of			Customer's Signature		Charge Summary		Total
Borneo Motors (Singapore) Pte Ltd							
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy



Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details	
THIRD PARTY CLAIM		S1000020 / TPCLAIM	Mdm Tan Peck Lin 222 Westwood Avenue #09-12 Singapore 648355 Mobile: 97508335	
		Document No.		
		0		
		Document Date		
		07/09/2024		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	ZRE210R	GEXGPZ S1	02/03/2020	EY0074X	0	32871	EY0074X

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MR2BE3BE000007236	1ZR0F14609	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
17	1	S51451-02190 COVER, ENGINE UNDER, <i>de</i>	1.00	164.00		✓164.00
18	2	S51410-02370 COVER ASSY, ENGINE U <i>7.Xan</i>	1.00	504.30		504.30
19	3	L90467-07220 CLIP <i>neu</i>	10.00	3.60		✓36.00
20	4	S52119-F2926 COVER, FR BUMPER L/C <i>de</i>	1.00	565.70		✓565.70
21	5	S52128-02924 COVER, FR BUMPER HOL <i>mi</i>	1.00	22.50		✓22.50
22	6	S53128-02260 GRILLE, RADIATOR, LW <i>cm</i>	1.00	37.80		✓37.80
23	7	S53112-02B90 GRILLE, RADIATOR, LW <i>cm</i>	1.00	511.60		✓511.60
24	8	S52421-02110 PAD, FR BUMPER <i>ku</i>	2.00	21.40		✓42.80
25	9	S16562-0T060 SEAL, RADIATOR TO SU <i>de</i>	1.00	31.50		✓31.50
26	0	S16563-0T060 SEAL, RADIATOR TO SU <i>de</i>	1.00	31.50		✓31.50
27	1	S52161-0K040 PIECE, RR BUMPER <i>neu</i>	10.00	5.80		✓58.00
28	2	S52125-02430 BRACKET, FOG LAMP MO <i>7.Xan</i>	1.00	84.90		84.90
29	3	S81481-02B00 COVER, FOG LAMP, RH <i>7.Xan</i>	1.00	119.40		119.40
30	4	S52126-02420 BRACKET, FOG LAMP MO <i>7.Xan</i>	1.00	84.90		84.90
31	5	S81482-02B00 COVER, FOG LAMP, LH <i>7.Xan</i>	1.00	119.40		119.40
32	6	S52115-02510 SUPPORT, FR BUMPER S <i>bt</i>	1.00	105.20		✓105.20
33	7	S52116-02500 SUPPORT, FR BUMPER S <i>bt</i>	1.00	105.20		✓105.20
34	8	S52611-02560 ABSORBER, FR BUMPER <i>cm</i>	1.00	125.30		✓125.30
35	9	S52021-02320 REINFORCEMENT SUB-AS <i>bt</i>	1.00	663.50		✓663.50
36	0	S57013-02210 BRACKET SUB-ASSY, FR <i>bt</i>	1.00	282.00		✓282.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Sublet	
		Lubrication/Fluid	
		Others	
			Less
			Amount Due

Inchcape

Borneo Motors



TOYOTA

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 PANDAN CRESCENT
 SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details				Account No.		Customer Details			
THIRD PARTY CLAIM				S1000020 / TPCLAIM		Mdm Tan Peck Lin 222 Westwood Avenue #09-12 Singapore 648355 Mobile: 97508335			
				Document No.					
				0					
				Document Date					
				07/09/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2020	ZRE210R	GEXGPZ S1	02/03/2020	EY0074X	0	32871	EY0074X		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
MR2BE3BE000007236		1ZR0F14609	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount	
37	1	S57014-02210	BRACKET SUB-ASSY, FR <i>lt</i>			1.00	351.50		351.50
38	2	T90467-05170	CLIP <i>re</i>			2.00	3.60		7.20
39	3	T53879-33030	RETAINER, FR FENDER <i>re</i>			4.00	17.00		68.00
40	4	T47749-33030	CLIP, PIN HOLD <i>re</i>			4.00	12.20		48.80
41	5	S53100-02E20	GRILLE ASSY, RADIATO <i>3m</i>			1.00	432.60		432.60
42	6	S53395-02280	SEAL, HOOD TO FR END <i>cut</i>			1.00	146.80		146.80
43	7	S53111-02D10	GRILLE, RADIATOR <i>com</i>			1.00	261.60		261.60
44	8	S52527-02070	RETAINER, FR BUMPER, <i>re</i>			1.00	37.00		37.00
45	9	L88210-33120	SENSOR ASSY, <i>? Xan</i>			1.00	3235.40		3235.40
46	0	S53301-02400	HOOD SUB-ASSY <i>lt</i>			1.00	1743.90		1743.90
47	1	T90541-09117	CUSHION <i>? Xan</i>			2.00	7.60		15.20
48	2	S53341-02410	INSULATOR, HOOD <i>? Xan</i>			1.00	647.10		647.10
49	3	T90467-09050	CLIP <i>re</i>			10.00	4.00		40.00
50	4	S53801-02270	FENDER SUB-ASSY, FR <i>lt</i>			1.00	999.40		999.40
51	5	S53802-02290	FENDER SUB-ASSY, FR <i>lt</i>			1.00	999.40		999.40
52	6	S53823-02211	PROTECTOR, FR SIDE <i>re</i>			1.00	30.60		30.60
53	7	S53824-02211	PROTECTOR, FR SIDE <i>re</i>			1.00	30.60		30.60
54	8	S53875-02A21	LINER, FR FENDER, RH <i>Xan</i>			1.00	565.40		565.40
55	9	S53876-02A61	LINER, FR FENDER, LH <i>Xan</i>			1.00	565.40		565.40
56	0	T90467-07214	CLIP <i>re</i>			10.00	3.80		38.00
For & on behalf of		Customer's Signature		Charge Summary		Total			
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less			
						Amount Due			

Inchcape
Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details				Account No.		Customer Details			
THIRD PARTY CLAIM				S1000020 / TPCLAIM		Mdm Tan Peck Lin 222 Westwood Avenue #09-12 Singapore 648355 Mobile: 97508335			
				Document No. 0					
				Document Date 07/09/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2020	ZRE210R	GEXGPZ S1	02/03/2020	EY0074X	0	32871	EY0074X		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
MR2BE3BE000007236		1ZR0F14609	60	Thomas Pang W T	--/--/----		0.00	--/--/----	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount	
57	1	T53510-12C40 LOCK ASSY, HOOD <i>bt</i>			1.00	188.00		✓ 188.00	
58	2	S53410-02570 HINGE ASSY, HOOD, RH <i>bt</i>			1.00	81.80		✓ 81.80	
59	3	S53420-02570 HINGE ASSY, HOOD, LH <i>bt</i>			1.00	81.80		✓ 81.80	
60	4	S53289-02090 COVER, RADIATOR SUPP <i>de</i>			1.00	274.30		✓ 274.30	
61	5	T90467-07217 CLIP <i>an</i>			10.00	3.60		✓ 36.00	
62	6	S16594-0T070 GUIDE, RADIATOR AIR <i>7Xan</i>			1.00	74.90		✓ 74.90	
63	7	S16593-0T170 GUIDE, RADIATOR AIR <i>7cm</i>			1.00	93.80		✓ 93.80	
64	8	S16595-0T190 GUIDE, RADIATOR AIR <i>2cm</i>			1.00	100.00		✓ 100.00	
65	9	S16592-0T240 GUIDE, RADIATOR AIR <i>2cm</i>			1.00	168.90		✓ 168.90	
66	0	S53205-02350 SUPPORT SUB-ASSY, RA <i>bt</i>			1.00	384.10		✓ 384.10	
67	1	S53213-02230 SUPPORT, RADIATOR, U <i>bt</i>			1.00	95.10		✓ 95.10	
68	2	S53214-02230 SUPPORT, RADIATOR, U <i>bt</i>			1.00	95.10		✓ 95.10	
69	3	S53203-02905 SUPPORT SUB-ASSY, RA <i>bt</i>			1.00	384.10		✓ 384.10	
70	4	S53202-02910 SUPPORT SUB-ASSY, RA <i>bt</i>			1.00	384.10		✓ 384.10	
71	5	T53248-47010 BRACKET, RADIATOR <i>an</i>			1.00	32.10		✓ 32.10	
72	6	T53249-47010 BRACKET, RADIATOR <i>an</i>			1.00	36.90		✓ 36.90	
73	7	S53028-02090 SUPPORT SUB-ASSY, RA <i>7Xan</i>			1.00	567.30		✓ 567.30	
74	8	S53208-02290 SUPPORT SUB-ASSY, HO <i>bt</i>			1.00	168.20		✓ 168.20	
75	9	S57101-02928 MEMBER SUB-ASSY, FR <i>reput</i>			1.00	1847.60		✓ 1847.60	
76	0	S57102-02945 MEMBER SUB-ASSY, FR <i>reput</i>			1.00	1936.00		✓ 1936.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total		
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due		

Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details				Account No.		Customer Details				
THIRD PARTY CLAIM				S1000020 / TPCLAIM		Mdm Tan Peck Lin 222 Westwood Avenue #09-12 Singapore 648355 Mobile: 97508335				
				Document No. 0						
				Document Date 07/09/2024						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks			
2020	ZRE210R	GEXGPZ S1	02/03/2020	EY0074X	0	32871	EY0074X			
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In	Collected On				
MR2BE3BE000007236		1ZR0F14609	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00		
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount	
77	1	T90975-02124	EMBLEM, SYMBOL <i>scr</i>				1.00	956.80		✓ 956.80
78	2	S81110-02U30	HEADLAMP ASSY, RH <i>cm</i>				1.00	5787.20		✓ 5787.20
79	3	S81150-02U20	HEADLAMP ASSY, LH <i>cm</i>				1.00	5787.20		✓ 5787.20
80	4	S85301-02230	INLET SUB-ASSY, WASH <i>Xnn</i>				1.00	89.40		89.40
81	5	S85315-02740	JAR, WASHER, A <i>Xnn</i>				1.00	200.80		200.80
82	6	S86510-0K010	HORN ASSY, HIGH PITCH <i>Xnn</i>				1.00	186.60		186.60
83	7	S86520-0K010	HORN ASSY, LOW PITCH <i>Xnn</i>				1.00	186.60		186.60
84	8	S884A0-F4040	CONDENSER ASSY, SUPP <i>Xnn</i>				1.00	2715.50		✓ 2715.50
85	9	S88703-F4040	HOSE SUB-ASSY, DISCH <i>? Xnn</i>				1.00	595.00		595.00
86	0	S88710-F4150	TUBE & ACCESSORY ASS <i>? Xnn</i>				1.00	1025.50		1025.50
87	1	S16400-0T400	RADIATOR ASSY <i>? Xnn</i>				1.00	3067.40		✓ 3067.40
88	2	S88703-F4040	HOSE SUB-ASSY, DISCH <i>? Xnn</i>				1.00	595.00		595.00
89	3	S88710-F4150	TUBE & ACCESSORY ASS <i>? Xnn</i>				1.00	1025.50		1025.50
90	4	S16400-0T400	RADIATOR ASSY <i>? Xnn</i>				1.00	3067.40		3067.40
91	5	S16361-0T540	FAN <i>? Xnn</i>				1.00	335.10		335.10
92	6	S16711-0T370	SHROUD, FAN <i>? Xnn</i>				1.00	366.90		366.90
93	7	T16363-47060	MOTOR, COOLING FAN <i>? Xnn</i>				1.00	1508.90		1508.90
94	8	S164A2-0T050	TANK, RESERVE SEALED <i>? Xnn</i>				1.00	210.50		210.50
95	9	S17700-0T270	CLEANER ASSY, AIR W/ <i>? cm</i>				1.00	1591.20		✓ 1591.20
96	0	S17752-0T110	INLET, AIR CLEANER, <i>? cm</i>				1.00	82.90		✓ 82.90
For & on behalf of			Customer's Signature		Charge Summary		Total			
Borneo Motors (Singapore) Pte Ltd			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due			

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details				Account No.		Customer Details			
THIRD PARTY CLAIM				S1000020 / TPCLAIM		Mdm Tan Peck Lin 222 Westwood Avenue #09-12 Singapore 648355 Mobile: 97508335			
				Document No. 0					
				Document Date 07/09/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2020	ZRE210R	GEXGPZ S1	02/03/2020	EY0074X	0	32871	EY0074X		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
MR2BE3BE000007236		1ZR0F14609	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00		
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount	
97	1	S17751-0T260 INLET, AIR CLEANER, <i>cm</i>			1.00	340.40		✓ 340.40	
98	2	S17753-0T090 INLET, AIR CLEANER, <i>cm</i>			1.00	120.30		✓ 120.30	
99	3	S08889-80102 COOLANT, SLLC&&& <i>he</i>			2.00	108.00		✓ 216.00	
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____ <i>Resue</i> <i>4p 900mold</i> <i>12 days + 1 = 13 days</i> <i>10/09/24</i> <i>Resy 64 paint</i>									
For & on behalf of Borneo Motors (Singapore) Pte Ltd				Customer's Signature		Charge Summary		Total 77,241.24	
Please acknowledge receipt of vehicle				Parts		51,047.60		GST 9.00% 6,951.71	
				Labour		26,113.64			
				Sublet		80.00			
				Lubrication/Fluid		0.00		Less 0.00	
				Others		0.00		Amount Due 84,192.95	