

*Not Authorised*

Date: 9-9-2024

Vehicle No: SGW6111U

Model: Tesla Model 3

Chassis: LRW3F7FS4RC022833

Reg.Year: 11.12.2023

*Permy Repair*

*3 days*

*83554.29*

Third Party Insurer: AIG

Third Party Veh No: SNL3513M

Date of Accident: 8/9/2024

Estimator: Loong

Surveyor:

## ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1		<i>CM</i> \$695.04
2	FRONT RH BUMPER RETAINER	1		<i>DIT</i> \$7.09
3	FRONT RH BUMPER SIDE SUPPORT BRACKET	1		<i>CM</i> \$11.28
4	FRONT BUMPER ENERGY ABSORBER	1		<i>Pr</i> \$21.34
5	FRONT BUMPER REINFORCEMENT	1		<i>R</i> \$372.34
6	FRONT RH BUMPER REINFORCEMENT BRACKET	1		<i>R</i> \$49.64
7	FRONT BUMPER LOWER REINFORCEMENT	1		<i>Pr R</i> \$49.64
8	FRONT RH BUMPER LOWER REINFORCEMENT BRACKET	1		<i>CM</i> \$29.90
9	FRONT BUMPER LOWER GRILLE COVER	1		<i>nd</i> \$91.01
10	FRONT RADIATOR SUPPORT PANEL	1		<i>CM</i> \$157.21
11	FRONT RH RADIATOR SUPPORT PANEL OUTER BRACKET	1		<i>Pr</i> \$7.09
12	FRONT BUMPER LOWER COVER	1		<i>DIT</i> \$182.03
13	FRONT RH HEADLAMP	1		<i>CM</i> \$1,580.39
14	FRONT RH FENDER LINER	1		<i>CM</i> \$106.73
15	FRONT RH KNUCKLE ARM	1		<i>Pr</i> \$463.36
16	FRONT RH KNUCKLE HUB + BEARING	1		<i>Pr</i> \$233.64
17	FRONT RH LOWER ARM - STRAIGHT	1		<i>Pr</i> \$212.65
18	FRONT RH LOWER ARM - CURVED	1		<i>Pr</i> \$212.65
19	FRONT RH UPPER ARM	1		<i>Pr</i> \$105.91
20	FRONT RH STEERING TIE ROD END	1		<i>Pr</i> \$121.49
21	FRONT PEDESTRIAN PROTECTION SENSOR	1		<i>Pr</i> \$46.04
22	RADIATOR	1		<i>Pr</i> \$79.43
23	RADIATOR FAN COWLING COMPLETE	1		<i>Pr</i> \$84.11
24	FRONT HOOD T LOGO	1		<i>Pr</i> \$41.37
25	FRONT HOOD	1		REPAIR
26	FRONT RH FENDER PANEL	1		REPAIR
SUB TOTAL				\$4,961.38
LESS 10%				-\$496.14
PARTS TOTAL				\$4,465.24

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1		<i>Pr</i> \$55.00
2	FRONT BUMPER RIVETS	1		<i>Pr</i> \$50.00
3	FRONT FENDER LINER CLIPS	1		<i>Pr</i> \$50.00
4	FRONT BUMPER UNDER COVER CLIPS	1		<i>Pr</i> \$50.00
5	RADIATOR COOLANT	1		<i>Pr</i> \$250.00

**Head office**

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

**Branch**

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

**Branch (Motor Insurance Claims)**

Blk 10 Ang Mo Kio Ind, Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 9-9-2024  
 Vehicle No: SGW6111U  
 Model: Tesla Model 3  
 Chassis: LRW3F7FS4RC022833  
 Reg.Year: 11.12.2023

Third Party Insurer: AIG  
 Third Party Veh No: SNL3513M  
 Date of Accident: 8/9/2024  
 Estimator: Loong  
 Surveyor:

		S/N TOTAL	\$455.00

**LABOUR CHARGES:**

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.		\$700.00	250/
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT BONNET, FRONT RH FENDER, ETC		\$800.00	440/
TO READJUST AND REALIGN HEADLAMP AIM		\$100.00	20/
TO REMOVE AND REFIT RADIATOR AND OTHER NECESSARY ITEMS TO ENABLE REPAIR	na	\$200.00	X
TO TUFF KOTE & UNDERSEAL MATERIALS.	na	\$150.00	X
TO DIAGNOSIS FAULT CODE & RESET MEMORY.	na	\$250.00	X
TO CHECK WIRING & ELECTRICAL SYSTEM.		\$100.00	20/
TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	na	\$150.00	X
TO REMOVE AND REFIT FRONT UNDERCARRIAGE PARTS TO ENABLE BODYWORK REPAIR	na	\$300.00	X
		<b>LABOUR TOTAL</b>	<b>\$2,750.00</b>

<b>TOTAL</b>	<b>\$7,670.24</b>
--------------	-------------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

