

Date: 9-9-2024
 Vehicle No: SGW6111U
 Model: Tesla Model 3
 Chassis: LRW3F7FS4RC022833
 Reg.Year: 11.12.2023

Not Authorised
Return Repair
3 days

Third Party Insurer: AIG
 Third Party Veh No: SNL3513M
 Date of Accident: 8/9/2024
 Estimator: Loong
 Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1		<i>CM</i> \$695.04
2	FRONT RH BUMPER RETAINER	1		<i>DIT</i> \$7.09
3	FRONT RH BUMPER SIDE SUPPORT BRACKET	1		\$11.28
4	FRONT BUMPER ENERGY ABSORBER	1		<i>Pn</i> \$21.34
5	FRONT BUMPER REINFORCEMENT	1		<i>R</i> \$372.34
6	FRONT RH BUMPER REINFORCEMENT BRACKET	1		<i>R</i> \$49.64
7	FRONT BUMPER LOWER REINFORCEMENT	1		<i>R</i> \$49.64
8	FRONT RH BUMPER LOWER REINFORCEMENT BRACKET	1		\$29.90
9	FRONT BUMPER LOWER GRILLE COVER	1		\$91.01
10	FRONT RADIATOR SUPPORT PANEL	1		\$157.21
11	FRONT RH RADIATOR SUPPORT PANEL OUTER BRACKET	1		\$7.09
12	FRONT BUMPER LOWER COVER	1		<i>DIT</i> \$182.03
13	FRONT RH HEADLAMP	1		<i>CM</i> \$1,580.39
14	FRONT RH FENDER LINER	1		\$106.73
15	FRONT RH KNUCKLE ARM	1		<i>Pn</i> \$463.36
16	FRONT RH KNUCKLE HUB + BEARING	1		<i>Pn</i> \$233.64
17	FRONT RH LOWER ARM - STRAIGHT	1		<i>Pn</i> \$212.65
18	FRONT RH LOWER ARM - CURVED	1		<i>Sn</i> \$212.65
19	FRONT RH UPPER ARM	1		<i>Sn</i> \$105.91
20	FRONT RH STEERING TIE ROD END	1		<i>Pn</i> \$121.49
21	FRONT PEDESTRIAN PROTECTION SENSOR	1		<i>Sn</i> \$46.04
22	RADIATOR	1		<i>Sn</i> \$79.43
23	RADIATOR FAN COWLING COMPLETE	1		<i>Pn</i> \$84.11
24	FRONT HOOD T LOGO	1		<i>Un</i> \$41.37
25	FRONT HOOD	1		REPAIR
26	FRONT RH FENDER PANEL	1		REPAIR
SUB TOTAL				\$4,961.38
LESS 10%				-\$496.14
PARTS TOTAL				\$4,465.24

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1		<i>Un</i> \$55.00
2	FRONT BUMPER RIVETS	1		<i>Un</i> \$50.00
3	FRONT FENDER LINER CLIPS	1		<i>Un</i> \$50.00
4	FRONT BUMPER UNDER COVER CLIPS	1		<i>Un</i> \$50.00
5	RADIATOR COOLANT	1		<i>Un</i> \$250.00

Date: 9-9-2024
 Vehicle No: SGW6111U
 Model: Tesla Model 3
 Chassis: LRW3F7FS4RC022833
 Reg.Year: 11.12.2023

Third Party Insurer: AIG
 Third Party Veh No: SNL3513M
 Date of Accident: 8/9/2024
 Estimator: Loong
 Surveyor:

		S/N TOTAL	\$455.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.			25cl	\$700.00
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT BONNET, FRONT RH FENDER, ETC			40cl	\$800.00
TO READJUST AND REALIGN HEADLAMP AIM			2cl	\$100.00
TO REMOVE AND REFIT RADIATOR AND OTHER NECESSARY ITEMS TO ENABLE REPAIR	nn	\$200.00	X	
TO TUFF KOTE & UNDERSEAL MATERIALS.	nn	\$150.00	X	
TO DIAGNOSIS FAULT CODE & RESET MEMORY.		\$250.00	7	
TO CHECK WIRING & ELECTRICAL SYSTEM.		\$100.00	2cl	
TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	nn	\$150.00	X	
TO REMOVE AND REFIT FRONT UNDERCARRIAGE PARTS TO ENABLE BODYWORK REPAIR	nn	\$300.00	X	
		LABOUR TOTAL		\$2,750.00

TOTAL	\$7,670.24
--------------	-------------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

