

Hup Ley Huat Motor Spray Painting Services

No.1 Kaki Bukit Ave 6 #01-35 AutoBay, Singapore 417883

TEL: 6746 0674 FAX: 6841 7639

Vehicle No : GBE 6183 R

Make: Nissan NV200

Date: 25/10/2023

Accident Date: 09/09/2024

Spare parts

QTY	List Price Price	(S\$)
1	Front Bumper Assembly	900 <i>de✓</i>
1	Front Bumper Bracket (Left Front)	43 <i>de✓</i>
1	Front Fender (Left, Front)	709.7 <i>bt✓</i>
1	Front Side Indicator Lamp (Left , Front)	85 <i>Xnn</i>
1	Fender Splash Shield (Left, Front)	208.02 <i>Xnn</i>
1	Front Fender- Finisher (Left, Front)	45.00 <i>Xnn</i>
1	Front Fender- Cover (Left, Front)	50.00 <i>Xnn</i>
1	Front Left Headlamp	1100 <i>Xnn</i>
1	Clips	50 <i>3one✓</i>

Spare Parts Subtotal

1682.70
10% - 1514.43

3190.72

Special Nett Items

Qty		
1	Sensor Set	250 <i>Xnn</i>
1	Rim Set (1 Pc) <i>Rim cover</i>	400 <i>180 cut</i>

650

Labour charges

S/N		(S\$)
1	To tuff coat affected areas	120 <i>30</i>
2	To spray paint include polishing and waxing on the changed body parts, repair body portions where consistent to the accident	600 <i>250</i>
3	To provide labour charges, workmanship to realign body structure and damaged consistent to the accident	600 <i>250</i>
4	Installation and wiring for sensor	120 <i>Xnn</i>

Labour charges: Subtotal

1514.43

1440

ESTIMATES PARTS AND LABOR GRAND TOTAL:

180
530
2224.43

5280.72

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanjik 97495749
WP 18/9/24
tanjik@lkkauto.com
1/5 Resurvey after repair
tanjik@lkkauto.com

4/5/1750
02 days