

ASS. REC. BY: Taufikh REF: CS/SMR 24 690180/TP3

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$13K  
 IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 2 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: GRE 6183R Yr Regn: 2016, 01  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Nissan NV200 c.c. 1461  
 Colour: Grey A/C: Insured / Std / NI / NA  
 Sp. Reading: 160514 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: VSKY BAM 2070120309  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Mod: CVT / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 185 / R14  
 R: L  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Tomvador  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 18/9/24  
 Survey held at Thump Lry Hmt  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Frt N/S  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Taufikh confirmed lump sum \$1750 and 2 days (red, \$3530.72, 66%)

Date/Time, File Pass to?

☐ : Prel. Report  
☐ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Report Format: \_\_\_\_\_

Days Of Repair: 2

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Invs (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

\$ + RS. \$ \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

# Hup Ley Huat Motor Spray Painting Services

No.1 Kaki Bukit Ave 6 #01-35 AutoBay, Singapore 417883  
TEL: 6746 0674 FAX: 6841 7639

Vehicle No : GBE 6183 R  
Make: Nissan NV200  
Date: 25/10/2023  
Accident Date: 09/09/2024

## Spare parts

QTY	List Price Price	(S\$)
1	Front Bumper Assembly	900 <i>de✓</i>
1	Front Bumper Bracket ( Left Front )	43 <i>de✓</i>
1	Front Fender (Left, Front)	709.7 <i>bt✓</i>
1	Front Side Indicator Lamp ( Left , Front )	85 <i>Xnn</i>
1	Fender Splash Shield (Left, Front)	208.02 <i>Xnn</i>
1	Front Fender- Finisher (Left, Front)	45.00 <i>Xnn</i>
1	Front Fender- Cover (Left, Front)	50.00 <i>Xnn</i>
1	Front Left Headlamp	1100 <i>Xnn</i>
1	Clips	50 <i>3are✓</i>

Spare Parts Subtotal

*1682.70*  
*10/- 1514.43* 3190.72

## Special Nett Items Qty

1	Sensor Set	250 <i>Xnn</i>
1	Rim Set ( 1 Pc ) <i>Rim cover</i>	<del>400</del> <i>180 cut</i>

650

## Labour charges

S/N		(S\$)
1	To tuff coat affected areas	120 <i>30</i>
2	To spray paint include polishing and waxing on the changed body parts, repair body portions where consistent to the accident	600 <i>250</i>
3	To provide labour charges, workmanship to realign body structure and damaged consistent to the accident	600 <i>250</i>
4	Installation and wiring for sensor	120 <i>Xnn</i>

Labour charges: Subtotal

*1514.43* 1440

ESTIMATES PARTS AND LABOR GRAND TOTAL:

5280.72

LKK Auto Consultants hence notify the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*Taufik 97495749*

*wp 18/9/24*

*taufik e lkkauto.com*

*1/5 Resurvey after repair*  
*taufik e lkkauto.com*

*180*  
*530*  
*2224.43*  
*4/5 1750*  
*02 days*