

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. : SAC2401410

INV Date : 18-11-2024

Reference CD/LPC24090181/Upa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SNU 3399D(SNM1530X)

Insured Veh. SKV 6740L

Claim No. 23/24/24/VP05/029823

Policy No. Z23VP05034195

Accident Date 04/09/2024

Inspection Date 16/09/2024

Description	Amount
Third Party Express Settlement	450.00
Sub-Total	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LONPAC INSURANCE BHD	Ref:	CD/LPC24090181/Upa3q2
300 BEACH ROAD	Date:	18/11/2024
#17-04/07 THE CONCOURSE SINGAPORE 199555	Code:	LPC2

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	SKV 6740L	Veh. Inspected	SNU 3399D(SNM1530X)
Policy No.	Z23VP05034195	Coverage	0
Claim No.	23/24/24/VP05/029823	Excess	\$0.00
Assign From	ENG HUEY NI	Assign Date	10/09/2024

2. Vehicle Details

Make & Model	TOYOTA ALPHARD 2.5S C-PACKAGE CVT	C.C	2493
Engine No.	2AR2885324	Year of Reg.	29/08/2023
Chassis No.	AGH300462034	Colour	BLACK
Odometer	6330 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	235/50R18	TOYO	8
L/H Front Tyre	235/50R18	TOYO	8
R/H Rear Tyre	235/50R18	TOYO	8
L/H Rear Tyre	235/50R18	TOYO	8

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/09/2024	Inspection Date	16/09/2024
Survey held at	Z-ONE AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVENUE 6 #01-87 AUTOBAY@KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNU 3399D(SNM1530X)

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR AXLE	NOT NECESSARY	\$4,363.80	\$0.00
1	REAR BUMPER	TO REPAIR SEE LABOUR	\$961.50	\$0.00
2	REAR BUMPER CENTER ULTRASONIC SENSOR RETAINER @\$28.20	NOT NECESSARY	\$56.40	\$0.00
2	REAR BUMPER CORNER ULTRASONIC SENSOR RETAINER @\$21.30	NOT NECESSARY	\$42.60	\$0.00
2	REAR BUMPER CUSHION @\$36.20	NOT NECESSARY	\$72.40	\$0.00
1	REAR BUMPER PLATE RH	NOT NECESSARY	\$27.20	\$0.00
1	REAR BUMPER SIDE SUPPORT NO.1	NOT NECESSARY	\$149.80	\$0.00
1	REAR BUMPER SIDE SUPPORT RH	NOT NECESSARY	\$157.10	\$0.00
1	REAR BUMPER UPPER COVER RH	NOT NECESSARY	\$401.90	\$0.00
1	REAR QUARTER PANEL OUTER PROTECTOR RH	CUT	\$414.10	\$414.10
1	REAR QUARTER PANEL RH (FENDER)	TO REPAIR SEE LABOUR	\$2,339.00	\$0.00
1	REAR SLIDING DOOR MOTOR UNIT RH	NOT NECESSARY	\$3,518.40	\$0.00
1	REAR SLIDING DOOR LOWER PROTECTOR RH	WARPED / CUT	\$1,123.00	\$1,123.00
1	REAR SLIDING DOOR RH	DENTED /BENT	\$3,256.70	\$2,998.10
1	REAR WHEEL HUB WITH BEARING ASSY RH	SERVICEABLE	\$1,608.90	\$0.00
1	REAR WHEELHOUSE INNER RH	NOT NECESSARY	\$1,106.30	\$0.00
1	REAR WHEELHOUSE LINER RH	NOT NECESSARY	\$359.90	\$0.00
1	REAR WHEELHOUSE OUTER RH	NOT NECESSARY	\$967.30	\$0.00
	LESS 25.00% DISCOUNT		(\$5,231.58)	(\$1,133.80)
			\$15,694.72	\$3,401.40

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR RIM RH (SN)	WARPED / CUT	\$2,592.23	\$600.00
1	REAR BUMPER CLIPS (SN)	NOT NECESSARY	\$50.00	\$0.00
1	REAR TYRE RH (SN)	NOT NECESSARY	\$380.00	\$0.00
			\$3,022.23	\$600.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	DIAGNOSE REPLACE AND /OR REPAIR TO RECTIFY REAR PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING		\$120.00	\$20.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE,REINSTALL REAR SUSPENSION AND UNDERCARRIAGE PART (TO FR)	NOT NECESSARY	\$450.00	\$0.00
	TO CONDUCT COMPUTERISE WHEEL ALIGNMENT AND ADJUSTMENTS		\$200.00	\$60.00
	TO RESPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT		\$1,600.00	\$800.00
	TO PROVIDE LABOUR TO CHARGE THE ABOVE ,PARTS AND REPAIR BODYWORK REALIGN BODYWORK ALIGNMENT AND DAMAGED CONSISTENT TO THE ACCIDENTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER ANDREAR QUARTER PANEL RH (FENDER).		\$1,400.00	\$500.00
	TO APPLY ANTI RUST CHEMICAL (TUFF-KOTE) ON REPAIRED AND REPLACED PANEL		\$150.00	\$30.00
			\$3,920.00	\$1,410.00
GRAND TOTAL			\$22,636.95	\$5,411.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$4,300.00
Report Ref No: CD/LPC24090181/Upa3q2				

MARKET VALUE: \$268,000.00(EST) LESS LTA REBATE: \$149,569.00(EST) = NETT VALUE :\$118,431.00(EST)

CKS



MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.


PHOTOGRAPHS FOR VEHICLE NO. : SNU 3399D(SNM1530X)




PHOTOGRAPHS FOR VEHICLE NO. : SNU 3399D(SNM1530X)



PHOTOGRAPHS FOR VEHICLE NO. : SNU 3399D(SNM1530X)



PHOTOGRAPHS FOR VEHICLE NO. : SNU 3399D(SNM1530X)



PHOTOGRAPHS FOR VEHICLE NO. : SNU 3399D(SNM1530X)



PHOTOGRAPHS FOR VEHICLE NO. : SNU 3399D(SNM1530X)



PHOTOGRAPHS FOR VEHICLE NO. : SNU 3399D(SNM1530X)



PHOTOGRAPHS FOR VEHICLE NO. : SNU 3399D(SNM1530X)



PHOTOGRAPHS FOR VEHICLE NO. : SNU 3399D(SNM1530X)



PHOTOGRAPHS FOR VEHICLE NO. : SNU 3399D(SNM1530X)





LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 11 of 21)


PHOTOGRAPHS FOR VEHICLE NO. : SNU 3399D(SNM1530X)



PHOTOGRAPHS FOR VEHICLE NO. : SNU 3399D(SNM1530X)



PHOTOGRAPHS FOR VEHICLE NO. : SNU 3399D(SNM1530X)






LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 14 of 21)

PHOTOGRAPHS FOR VEHICLE NO. : SNU 3399D(SNM1530X)



PHOTOGRAPHS FOR VEHICLE NO. : SNU 3399D(SNM1530X)



PHOTOGRAPHS FOR VEHICLE NO. : SNU 3399D(SNM1530X)





LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 17 of 21)

PHOTOGRAPHS FOR VEHICLE NO. : SNU 3399D(SNM1530X)





PHOTOGRAPHS FOR VEHICLE NO. : SNU 3399D(SNM1530X)



PHOTOGRAPHS FOR VEHICLE NO. : SNU 3399D(SNM1530X)




PHOTOGRAPHS FOR VEHICLE NO. : SNU 3399D(SNM1530X)



PHOTOGRAPHS FOR VEHICLE NO. : SNU 3399D(SNM1530X)



PHOTOGRAPHS FOR VEHICLE NO. : SNU 3399D(SNM1530X)





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SNU 3399D(SNM1530X)

