

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Bldg D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE GST Registration No. 201118055N Company Registration No: 201118055N

not Authorised
1/5 #4300/
3 days.
Wk Mr. Henry--
16/9/24

ESTIMATE

Tang Chee Kuan
53 Sunrise Avenue, #03-22 Singapore 806746
Contact : 92489863-Wife 82184292

Code : C102119
Date in : 16/09/2024
Vehicle Num. : SNM1530X
Model : Toyota Alphard 2.5S C-Package CVT
Chassis/Eng# : AGH300462034/2AR2885324

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
Rear axle 11	1	4363.80	4,363.80 X
Rear bumper 11	1	961.50	961.50 X
Rear bumper center ultrasonic sensor retainer 11	2	28.20	56.40 X
Rear bumper corner ultrasonic sensor retainer 11	2	21.30	42.60 X
Rear bumper cushion 11	2	36.20	72.40 X
Rear bumper plate RH 11	1	27.20	27.20 X
Rear bumper side support no.1 11	1	149.80	149.80 X
Rear bumper side support RH 11	1	157.10	157.10 X
Rear bumper upper cover RH 11	1	401.90	401.90 X
Rear quarter panel mudguard RH outer protector RH 1 cut	1	414.10	414.10 ✓
Rear quarter panel RH (FENDER) 11	1	2339.00	2,339.00 X
Rear rim RH cut/magnd	1	3456.30	3,456.30 600 S/W
Rear sliding door motor unit RH 11	1	3518.40	3,518.40 X
Rear sliding door mudguard RH lower protector RH cut/magnd	1	1123.00	1,123.00 ✓
Rear sliding door RH 11/3mf	1	3256.70 2998.10	3,256.70 ✓
Rear wheel hub with bearing assy RH 11	1	1608.90	1,608.90 X
Rear wheelhouse inner RH 11	1	1106.30	1,106.30 X



Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE GST Registration No. 201118055N Company Registration No: 201118055N

Rear wheelhouse liner RH	1	359.90	359.90	X
Rear wheelhouse outer RH	1	967.30	967.30	X
Subtotal before discount			24,382.60	
Percentage discount 25%			6,095.65	
Sub-total 1			18,286.95	
Rear bumper clips (SN)	1	50.00	50.00	X
Rear tyre RH (SN)	1	380.00	380.00	X
Subtotal before discount			430.00	
Percentage discount 0%			0.00	
Sub-total 2			430.00	
Parts-total			18,716.95	

LABOUR

Description	Price
Diagnose, replace and/or repair to rectify rear portion electrical system for proper functioning.	120.00
To remove, reinstall rear suspension and undercarriage part. (to FR)	450.00
To conduct computerise wheel alignment and adjustments	200.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,600.00
To provide labour to change the above, parts and repair bodywork, re-align bodywork alignment and damaged consistent to the accidents.	1,400.00
To apply anti-rust chemical (Tuff-Kote) on repaired and replaced panel.	150.00
Labour Total	3,920.00
Parts & Labour Total	22,636.95

P- 4536.2
252
P- 3401.40
S.N- 600
L- 1410
5411.40
202
4329