

TP

**SMRT Accident Vehicle Repair Estimates**

SMRT Autor  
60 Woodlanc  
FAX Number  
Estimator Te  
Accident Rep  
Date Gener  
User ID

China Taiping  
ADV RH LH 1/2 RR

Section A - Accident Details	
Registration Number	SHD6493E
Case Reference Number	TAX/09/24/2008
Registration Date	1/11/17
Company Type	Strides Premier Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	TONG CHEE MENG
Type of Accident	Head to Rear
Accident Date and Time	4/9/24 10:28 AM
Accident Reported Date and Time	4/9/24 11:38 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24122377
Special Instruction to ARC,if any	TP/REAR PORTION
Prepared Date and Time	9/9/24 11:07 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, If applicable
Total Labour Cost	\$676.00	\$0.00
Total Spray Cost	\$818.00	\$0.00
Total Spare Part Cost	\$2,295.95	\$0.00
Total Other Cost	\$945.32	\$0.00
<b>TOTAL COST</b>	<b>\$4,735.27</b>	<b>\$0.00</b>
<b>Lump Sum Total</b>	<b>\$4,750.00</b>	<b>\$0.00</b>
Number of Repair Days	5.0	
Prepared / Adjusted By	Mun San #	
ARC / Surveyor Sign Off Date		
Signature	<i>8w</i>	<i>Steve CLKK</i> <i>19/9/24, 4.11/2</i> <i>W k</i>
Remarks		<i>L/S</i> <i>W M S W</i>

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

3 days

**SMRT Accident Vehicle Repair Estimates**

SMRT Autor  
60 Woodlanc  
FAX Number  
Estimator Te  
Accident Ref

Date Genera

User ID

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicab
TO REPAIR REAR PORTION	\$676.00	200
<b>Total Labour</b>	<b>\$676.00</b>	

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicab
TO RESPRAY <i>Rear</i> FRONT BUMPER	\$378.00	200
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$220.00	200 100
TO RESPRAY BUMPER BEAM	\$220.00	100
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$818.00</b>	<b>400</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicab
TO WASH AND VACUUM	\$60.00	X nn
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER (NET)	\$445.32	- n/c
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	X nn
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	X nn
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	20 - n/c
TO REPLACE SUNDRY PARTS	\$100.00	X nn
<b>Total Other Costs</b>	<b>\$945.32</b>	<b>465.32</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
		5215947913	COVER, RR BUMPER ASSY	1.00	\$478.90	25.00	\$359.17	Replace	-X- R / BR
		5202347030	REAR BUMPER REINFORCEMENT	1.00	\$360.10	25.00	\$270.08	Replace	? x nn
		5246247030	PAD, RR BUMPER, RH & LH, 1	2.00	\$4.30	25.00	\$6.45	Replace	X nn
		5246247020	PAD, RR BUMPER, RH & LH, 2	2.00	\$4.30	25.00	\$6.45	Replace	X nn
		5246247010	PAD, RR BUMPER, RH & LH, 3	2.00	\$4.30	25.00	\$6.45	Replace	X nn
		5246147010	PAD, RR BUMPER, CTR	3.00	\$2.50	25.00	\$5.63	Replace	X nn
		5216116010	CLIPS PIECE, FRT BUMPER	10.00	\$4.80	35.00	\$31.20	Replace	X nn
		5245347010	GUARD, RR BUMPER, LOWER	1.00	\$623.50	25.00	\$467.63	Replace	- c47
		5216947020	COVER, GUARD RR BUMPER LOWER	1.00	\$16.70	25.00	\$12.52	Replace	- c47
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	X nn
		8999730100	ANTENNA, ELECTRICAL KEY	1.00	\$78.00	25.00	\$58.50	Replace	X ? x nn
		5839847050	COVER, REAR FLOOR UNDER, RH	1.00	\$189.20	25.00	\$141.90	Replace	X nn
		5839947030	COVER, REAR FLOOR UNDER, LH	1.00	\$261.60	25.00	\$196.20	Replace	X nn
		8825047010	COVER, REAR FLOOR UNDER CENTER	1.00	\$249.10	25.00	\$186.83	Replace	X nn
		7680147110A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1.00	\$992.30	25.00	\$744.22	Replace	X R
		7544147090	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1.00	\$59.10	25.00	\$44.33	Replace	- n/c
		7544247130	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1.00	\$59.10	25.00	\$44.33	Replace	- n/c

**SMRT Accident Vehicle Repair Estimates**

SMRT Autor  
60 Woodlane  
FAX Number  
Estimator Te  
Accident Rep

Date Gener  
User ID

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
		7540348010	EMBLEM SUB-ASSY REAR	1.00	\$77.40	25.00	\$58.05	Replace X	nn
			STICKER LOGO ( TAILGATE )	2.00	\$25.00	0.00	\$50.00	Replace /	nn
<b>Total</b>					<b>\$3,670.20</b>		<b>\$2,869.94</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Cl
<b>Total</b>									

977.98  
-20% lump-sum  
782.38  
  
+ 1065.32  
  
= 1847.70  
1850