


Section A - Accident Details

Registration Number	SHD6493E
Case Reference Number	TAX/09/24/2008
Registration Date	1/Nov/2017
Company Type	Strides Premier Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	TONG CHEE MENG
Type of Accident	Head to Rear
Accident Date and Time	4/Sep/2024 10:28 AM
Accident Reported Date and Time	4/Sep/2024 11:38 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24122377
Special Instruction to ARC,if any	TP/REAR PORTION
Prepared Date and Time	9/Sep/2024 11:07 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$200.00
Total Spray Cost	\$1,038.00	\$400.00
Total Spare Part Cost	\$2,799.35	\$782.38
Total Other Cost	\$945.32	\$465.32
TOTAL COST	\$5,458.67	\$1,847.70
Lump Sum Total	\$5,450.00	\$1,850.00 (L/S)
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Mun San #	STEVE CHEN (LKK) / China Taiping
ARC / Surveyor Sign Off Date	13/09/2024 4:13 PM	12/09/2024 5:44 PM
Signature		
Remarks	INITIAL = 5 DAYS WITH SUPP = 0 DAY TOTAL = 5 DAYS	Expected length of repair (days) = 3 days Expected release date of vehicle after repair (Subject to approval from FM and with Supplementary) = 18-09-2024 INITIAL = 3 DAYS EXTEND = 0 DAY L/S REPAIR / AFTER PAINT PHOTO . FOR CHECK ITEM and REPLACE ITEM . PLEASE CALL SURVEYOR STEVE CHEN (LKK) / HP : 010-9429 541 / Email : stevechen@lkkauto.com

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2409-0282	Invoice Number	
Quotation Date	25.09.2024	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$676.00	\$200.00
Total Labour	\$676.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY BUMPER BEAM	\$220.00	\$100.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$220.00	\$100.00
TO RESPRAY BUMPER BEAM	\$220.00	\$0.00
Total Spray Painting & Panel Beating	\$1,038.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$445.32	\$445.32
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$945.32	\$465.32

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
			STICKER LOGO (TAILGATE)	2.00	\$25.00	0.00	\$50.00	Replace	Replace	✓
		7540348010	EMBLEM SUB-ASSY REAR	0.00	\$77.40	0.00	\$0.00	Replace	Not Given	X
		7544247130	NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT	1.00	\$59.10	25.00	\$44.33	Replace	Replace	✓
		7544147090	NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT	1.00	\$59.10	25.00	\$44.33	Replace	Replace	✓
		7680147110A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	1.00	\$992.30	100.00	\$0.00	Replace	Repair	R
		6625947010	COVER, REAR FLOOR UNDER CENTER	0.00	\$249.10	0.00	\$0.00	Replace	Not Given	X
		5839947030	COVER, REAR FLOOR UNDER , LH	0.00	\$261.60	0.00	\$0.00	Replace	Not Given	X
		5839847050	COVER, REAR FLOOR UNDER , RH	0.00	\$189.20	0.00	\$0.00	Replace	Not Given	X

Strides Premier Accident Vehicle Repair Estimates

Strides Premier Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 25/09/2024

User ID : PohSuan

		8999730100	ANTENNA, ELECTRICAL KEY	0.00	\$78.00	0.00	\$0.00	Replace	Check	X
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X
		5216947020	COVER, GUARD RR BUMPER LOWER	1.00	\$16.70	25.00	\$12.52	Replace	Replace	√
		5245347010	GUARD, RR BUMPER, LOWER	1.00	\$623.50	25.00	\$467.63	Replace	Replace	√
		5216116010	CLIPS PIECE, FRT BUMPER	0.00	\$4.80	0.00	\$0.00	Replace	Not Given	X
		5246147010	PAD, RR BUMPER, CTR	0.00	\$2.50	0.00	\$0.00	Replace	Not Given	X
		5246247010	PAD, RR BUMPER, RH & LH , 3	0.00	\$4.30	0.00	\$0.00	Replace	Not Given	X
		5246247020	PAD, RR BUMPER, RH & LH , 2	0.00	\$4.30	0.00	\$0.00	Replace	Not Given	X
		5246247030	PAD, RR BUMPER, RH & LH , 1	0.00	\$4.30	0.00	\$0.00	Replace	Not Given	X
		5202347030	REAR BUMPER REINFORCEMENT	0.00	\$360.10	0.00	\$0.00	Replace	Check	X
		5215947913	COVER, RR BUMPER ASSY	1.00	\$478.90	100.00	\$0.00	Replace	Repair	R
Total					\$3,670.20		\$618.81			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
		5202347030	REAR BUMPER REINFORCEMENT	1.00	\$360.10	100.00	\$0.00	Replace	Repair	R
		5215947913	COVER, RR BUMPER ASSY	1.00	\$478.90	25.00	\$359.17	Replace	Replace	√
Total					839.00		359.17			

	977.98	
	-20%	
	<u>782.38</u>	L/S \$1,850/-
+	200.00	
+	<u>865.32</u>	
	1,847.70	