



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLQ 6918G

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SUNDRIES (SN)	NECESSARY	\$50.00	\$20.00
1	TRIM BUMPER (SN)	TO REPAIR SEE LABOUR	\$2,001.83	\$0.00
12	BLIND RIVET (SN)	NOT NECESSARY	\$66.00	\$0.00
1	MOUNTING RAIL LH (SN)	NOT NECESSARY	\$14.89	\$0.00
1	LAMP UNIT LH (SN)	CRACKED	\$3,989.21	\$3,989.21
1	TRIM, BUMPER (SN) (ADDITIONAL)	CRACKED	\$2,001.83	\$2,001.83
1	ENGINE COMPARTMENT COVER LH (SN) (ADDITIONAL)	CRACKED	\$104.17	\$104.17
1	BASIC CARRIER, BUMPER LH (SN) (ADDITIONAL)	BENT	\$119.18	\$119.18
1	IMPACT ABSORBER (SN) (ADDITIONAL)	CRACKED	\$239.34	\$239.34
1	CONTROL UNIT, COMPLETE (SN) (ADDITIONAL)	SHORTED	\$884.17	\$884.17
20	BLIND RIVET (SN) (ADDITIONAL)	NECESSARY	\$110.00	\$110.00
			\$9,580.62	\$7,467.90

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REPLACE FRONT BUMPER & AFFECTED AREA REPAIR ON FRONT LH FENDER. INCLUSIVE OF THE REPAIR OF TRIM BUMPER	NOT NECESSARY	\$1,050.00	\$450.00
	PAINT WORK ON FRT BUMPER & FRONT LH FENDER		\$600.00	\$560.00
	REMOVE & INSTALL FRONT PARKING ASSIST FOR FACILITATE REPAIR		\$120.00	\$80.00
	APPLY SEALANT ON AFFECTED AREA		\$100.00	\$0.00
	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM		\$160.00	\$100.00
	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM		\$500.00	\$500.00
			\$2,530.00	\$1,690.00

GRAND TOTAL			\$12,110.62	\$9,157.90
--------------------	--	--	--------------------	-------------------

	RECOMMENDED COST OF REPAIRS			\$9,157.90
--	------------------------------------	--	--	-------------------

Report Ref No: CS/GAI24090184/Rvp3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.