



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24090185/Uvp3
(BUDGET DIRECT INSURANCE)	Date:	27/09/2024
190 CLEMENCEAU AVENUE #03-01	Code:	AGI
SINGAPORE SHOPPING CENTRE SINGAPORE 239924		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLG 6764K	Veh. Inspected	SKM 6220T
Policy No.	P10643440R03	Coverage	0
Claim No.	C10031571/CH	Excess	\$0.00
Assign From	NG CHEN HOW	Assign Date	10/09/2024

2. Vehicle Details

Make & Model	TOYOTA CAMRY HYBRID (A)	C.C	2494
Engine No.	2ARU059270	Year of Reg.	25/03/2014
Chassis No.	MR053CK5004016008	Colour	BLACK
Odometer	63502 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/55R17	YOKOHAMA	6
L/H Front Tyre	215/55R17	YOKOHAMA	6
R/H Rear Tyre	215/55R17	YOKOHAMA	6
L/H Rear Tyre	215/55R17	YOKOHAMA	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/09/2024	Inspection Date	16/09/2024
Survey held at	AUTOBACS CAR CARE (S) PTE LTD 8 KAKI BUKIT AVENUE 4 #08-40/45/46 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days