

**AUTOBACS CAR CARE (SINGAPORE) PTE. LTD.**

8 Kaki Bukit Ave 4 #08-40/45/46 Premier@Kaki Bukit S(415875)

Tel : 6702 1555 Fax : 6702 1444

Co. Reg No. : 201500047H GST No. : 201500047H

Email : st.sim@autobacs.com.sg

Not Authorised
in
moray
16/9/24
1/c = 2000/
3 days
Elaph-Aphay

TO	: AUTO & GENERAL (SLG6764K)	DATE	: 10-Sep-24
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
OWNER PARTICULAR			
OWNER ID	: XXXXXX522M	P -	
		S -	
		L -	
VEHICLE DETAILS			
VEHICLE NO.	: SKM6220T	TOTAL	:
MODEL / MAKE	: TOYOTA CAMRY	L/S -20%	:
CHASSIS NO.	: MR053CK5004016008	SUB TOTAL	:
ACCIDENT DETAIL			
DATE	: 8-Sep-24		
TIME	: 16:30 HRS	CONTACT PERSON	: MR. SIM 9844 0974

QUOTATION SUMMARY PAGE 01**CLAIMS DETAIL : PARTS LIST**

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>DS/DE</i>	1	\$ 578.00	\$ 578.00
2	FOG LAMP GARNISH <i>grat</i>	1	\$ 70.00	\$ 70.00
3	F/R HEADLAMP <i>one</i>	1	\$ 1,800.00	\$ 1,800.00
4	F/R FOG LAMP <i>one</i>	1	\$ 300.00	\$ 300.00
TOTAL PRICE				\$ 2,748.00
LESS -25%				\$ (687.00)
SUB TOTAL PRICE				\$ 2,061.00

QUOTATION SUMMARY PAGE 02**CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING**

TO LABOUR CHARGE FOR REMOVING FRONT BUMPER OUT TO FACILITATE REPLACEMENT OF DAMAGED PARTS	\$ 300.00	200	
TO RESPRAY FRONT BUMPER	\$ 300.00	✓	
TOTAL	\$ 600.00		

ESTIMATE REPORT

TOTAL PARTS COST	:	\$ 2,061.00
TOTAL LABOUR COST	:	\$ 600.00
TOTAL REPAIR COST	:	\$ 2,661.00

APPROVED DETAILS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: