



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24090186/Unh3
75 BRAS BASAH ROAD	Date:	04/10/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBU 6335K	Veh. Inspected	SNP 6681U
Policy No.	-	Coverage	0
Claim No.	MT/1294540-001	Excess	\$0.00
Assign From	RAJESWARY	Assign Date	10/09/2024

2. Vehicle Details

Make & Model	MERCEDES BENZ C180 (A)	C.C	1497
Engine No.	26491530180668	Year of Reg.	18/01/2021
Chassis No.	WDD2050762R541977	Colour	GREY
Odometer	67315 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/50ZR17	MICHELIN	6
L/H Front Tyre	225/50ZR17	MICHELIN	6
R/H Rear Tyre	225/50ZR17	MICHELIN	6
L/H Rear Tyre	225/50ZR17	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/09/2024	Inspection Date	25/09/2024 (10:13)
Survey held at	PING MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6,#01-25,AUTOBAY@KAKI BUKIT,SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days