



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555		Ref: Date: Code:	CS3/LPC24060155/Tvh3e2 17/07/2024 LPC2	
1. Policy Particulars :- PRE-REPAIR SURVEY				
Insured Veh.	GBC 394Z	Veh. Inspected	FBQ 778B	
Policy No.	-	Coverage	0	
Claim No.	24/24/24/VC05/029255	Excess	\$0.00	
Assign From	CHARMAINE KONG	Assign Date	19/06/2024	
2. Vehicle Details				
Make & Model	YAMAHA MX KING	C.C	150	
Engine No.	G3E6E0506063	Year of Reg.	23/07/2019	
Chassis No.	MH3UG0750KK026945	Colour	RED	
Odometer	- KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: NIL			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	90/80 R17	MAXXIS	5	
L/H Front Tyre	90/80 R17	MAXXIS	5	
R/H Rear Tyre	90/80 R17	MAXXIS	5	
L/H Rear Tyre	90/80 R17	MAXXIS	5	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT, REAR PORTION AND N/S BODY.				
5. General Information				
Accident Date	14/05/2024	Inspection Date	19/06/2024 (05:00PM)	
Survey held at	464 MACPHERSON ROAD SINGAPORE 368182 - MOTO 51 PTE LTD			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

MTH

MOHAMAD TAUFIKH

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.