



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS LONPAC INSURANCE BHD		Ref:		CS3/LPC24060155/Tvh3e2
300 BEACH ROAD		Date:		17/07/2024
#17-04/07 THE CONCOURSE SINGAPORE 199555		Code:		LPC2
<b>1. Policy Particulars :- PRE-REPAIR SURVEY</b>				
	Insured Veh.	GBC 394Z	Veh. Inspected	FBQ 778B
	Policy No.	-	Coverage	0
	Claim No.	24/24/24/VC05/029255	Excess	\$0.00
	Assign From	CHARMAINE KONG	Assign Date	19/06/2024
<b>2. Vehicle Details</b>				
	Make & Model	YAMAHA MX KING	C.C	150
	Engine No.	G3E6E0506063	Year of Reg.	23/07/2019
	Chassis No.	MH3UG0750KK026945	Colour	RED
	Odometer	- KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: NIL		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance (mm)
	R/H Front Tyre	90/80 R17	MAXXIS	5
	L/H Front Tyre	90/80 R17	MAXXIS	5
	R/H Rear Tyre	90/80 R17	MAXXIS	5
	L/H Rear Tyre	90/80 R17	MAXXIS	5
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT, REAR PORTION AND N/S BODY.				
<b>5. General Information</b>				
	Accident Date	14/05/2024	Inspection Date	19/06/2024 (05:00PM)
	Survey held at	464 MACPHERSON ROAD SINGAPORE 368182 - MOTO 51 PTE LTD		
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				