



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS LONPAC INSURANCE BHD		Ref:		CS3/LPC24060155/Tvh3e2
300 BEACH ROAD		Date:		17/07/2024
#17-04/07 THE CONCOURSE SINGAPORE 199555		Code:		LPC2
1. Policy Particulars :- PRE-REPAIR SURVEY				
	Insured Veh.	GBC 394Z	Veh. Inspected	FBQ 778B
	Policy No.	-	Coverage	0
	Claim No.	24/24/24/VC05/029255	Excess	\$0.00
	Assign From	CHARMAINE KONG	Assign Date	19/06/2024
2. Vehicle Details				
	Make & Model	YAMAHA MX KING	C.C	150
	Engine No.	G3E6E0506063	Year of Reg.	23/07/2019
	Chassis No.	MH3UG0750KK026945	Colour	RED
	Odometer	- KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: NIL		
3. Conditions of Tyres				
		Size	Make	Balance (mm)
	R/H Front Tyre	90/80 R17	MAXXIS	5
	L/H Front Tyre	90/80 R17	MAXXIS	5
	R/H Rear Tyre	90/80 R17	MAXXIS	5
	L/H Rear Tyre	90/80 R17	MAXXIS	5
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT, REAR PORTION AND N/S BODY.				
5. General Information				
	Accident Date	14/05/2024	Inspection Date	19/06/2024 (05:00PM)
	Survey held at	464 MACPHERSON ROAD SINGAPORE 368182 - MOTO 51 PTE LTD		
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

MTH

MOHAMAD TAUFIKH

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.