



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBM 2293R

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	TO REPAIR SEE LABOUR	\$1,230.00	\$0.00
1	REAR BUMPER RETAINER LH	NOT NECESSARY	\$89.00	\$0.00
	LESS 10.00% DISCOUNT		(\$131.90)	\$0.00
			\$1,187.10	\$0.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR TO FACILITATE REPAIR. INCLUSIVE OF THE REPAIR OF REAR BUMPER		\$300.00	\$250.00
	TO RESPRAY AFFECTED AREAS		\$300.00	\$250.00
			\$600.00	\$500.00
GRAND TOTAL			\$1,787.10	\$500.00
RECOMMENDED COST OF REPAIRS				\$500.00
Report Ref No: CS/TP24090188/Rnh3m4				

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.