

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24090193/AUA3Q2**Date:** 07/01/2025**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7240043624
Claimant Vehicle No :	SMK3898U	Insured Vehicle No :	GBE8173G
Date of Loss:	07/09/2024	Nature of Claim:	TP
		Claim No:	5311523442SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK3898U	Engine No:	A25A0139434
Make & Model:	TOYOTA CAMRY, 2.5 HYBRID (A)	Chassis No:	AXVH701027080
Reg. Date:	08/03/2019 (Man. Year: 2018)	Odometer:	137012 km
Colour:	White		
Engine Capacity:	2487 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,486.62	2,818.75	3,667.87	56.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,650.00	1,380.00	1,270.00	47.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,136.62	4,198.75	4,937.87	54.04
Approved Total (Overridden) (S\$)		3,350.00		
(S\$)	9,136.62	3,350.00	5,786.62	63.33
+ GST 9.00/9.00% (S\$)	822.30	301.50	520.80	63.33
Nett Amount (S\$)	9,958.92	3,651.50	6,307.42	63.33
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		4,053.68		

INSPECTION

Date of Assignment:	12/09/2024		
Date Inspected:	12/09/2024	Inspected At:	Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58 Singapore 408717
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** NA MENG YAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	994.50 FL	*994.50 FL
2	2		*REAR BUMPER SIDE HOLDER LH& RH	Not Necessary	291.00 FL	*- FL
3	2		*REAR BUMPER REFLECTOR LH&RH	Not Necessary	344.40 FL	*- FL
4	1		*REAR BUMPER LOWER GARNISH	Cut	503.90 FL	*503.90 FL
5	2		*REAR BUMPER SENSOR	Damaged (1 PCS ONLY)	590.20 FL	*295.10 FL
6	1		*REAR BUMPER REINFORCEMENT	Not Necessary	455.70 FL	*- FL
7	1		*REAR END PANEL	Repair	788.50 FL	*- FL
8	1		*REAR END PANEL TOP GARNISH	Deformed	356.10 FL	*356.10 FL
9	2		*TAILLAMP LH & RH	Not Necessary	1,760.20 FL	*- FL
10	1		*BOOTLID	Dented	1,373.90 FL	*1,373.90 FL
11	1		*BOOTLID LOCK	Not Necessary	480.20 FL	*- FL
12	1		*BOOTLID WEATHERSTRIPE	Not Necessary	395.40 FL	*- FL
13	1		*TOYOTA LOGO	Necessary	80.60 FL	*80.60 FL
14	1		*HYBRID EMBLEM	Necessary	60.90 FL	*60.90 FL
15	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
16	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
17	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,605.50	3,735.00
- List Item Discount on L Items 25.00/25.00% (\$)	2,118.88	916.25
Total Parts (\$)	6,486.62	2,818.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	1,000.00	500.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	1,000.00	600.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO APPLY TUFF COAT	New	100.00	40.00
5	TO REMOVE UPHOLSTERY	New	150.00	30.00
6	TO REMOVE REVERSE SENSOR	New	100.00	50.00
7	TO REMOVE REAR CAMERA	New	100.00	50.00
8	TO TRANSFER BOOTLDI FITTINGS	New	150.00	80.00
			Gross Labour Cost (\$\$)	2,650.00
				1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >