

REF: CS/CTI24090194/Avh3

ASSIGNMENT

From: _____ Date: _____

Estim: _____

OD / TP RES / TP RES / OD RES / EVA / INV / MVTo in Vehicle No: _____at W/O _____

of _____

Insured: **SMG 3122X**

Policy No: _____

Claim's No: **SNM24D205108**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SMN4120H** Yr Regn: **2007/Dec**Type: M. Car / M. Cycle / Brs / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Toyota Estima** C.D. **2362**Colour: **Black** A/C: Insured / Std / NI / NASp. Reading: **296207** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **ACR500056525**Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **215/55R17**R: **215/55R17**

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: **Viking**R/Bal. **06** mm R/Bal. **06** mmL/Bal. **06** mm L/Bal. **06** mmD.O.A. **11/9/2024** D.O.I. **11/09/24**Survey held at **NSI**Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Claim**20/12/24** **Adrian confirmed LS \$15,500 (red 32,450.40, 67%)**COE Expiry: **30/11/2027**Estimate given during: **Yes** ☒
1st Survey: **No** ☐MV: **451K**PV: **16.2K**Nett: **28.8K**

Date/Time, File Pass to?

☐: Preli. Report

1)

☐: Final Report

Date/Time, File Return to?

2)

Report Format:

Report 24 Hrs / 1 P. 1 C.

Days Of Repair: **11**

Resurvey No. of Trip: _____

Add Fee: ☐: Site Insp (\$ _____)☐: Interview (\$ _____)☐: Tech. Insp (\$ _____)

Survey Fee:

Transportation:

3 + R.S. \$1

Photos

Others



Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

YAHYA BIN MOHAMED
BLK 475 SEMBAWANG DR #01-323
SINGAPORE 750475

Contact : 92309662

TAX INVOICE

Repair Code : CLM18371

Date in : 11/09/2024

Vehicle Num. : SMN4120H

Model : TOYOTA ESTIMA AERAS 2.4 A

Chassis/Eng# : ACR500056525/2AZF103526

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIRCON CONDENSER <i>Replaced</i>	1	2644.50	2,644.50
AIRCON CONDENSER DISCHARGE PIPE <i>Replaced</i>	1	762.10	762.10
AIRCON CONDENSER SUCTION PIPE <i>Replaced</i>	1	928.20	928.20
AIRCON FAN BLADE <i>Replaced</i>	1	383.70	383.70
AIRCON FAN MOTOR <i>Replaced</i>	1	892.90	892.90
FRONT BONNET <i>Replaced</i>	1	1033.40	1,033.40
FRONT BONNET HINGES L/R <i>Replaced</i>	2	78.60	157.20
FRONT BONNET MECHANISM LOCK <i>Replaced</i>	1	186.90	186.90
FRONT BONNET TOP RUBBER SEAL <i>Replaced</i>	1	62.50	62.50
FRONT BRACE PANEL <i>Replaced</i>	1	95.20	95.20
FRONT BUMPER <i>Replaced</i>	1	3772.70	3,772.70
FRONT BUMPER FOGLAMP GARNISH L/R <i>Replaced</i>	2	137.40	274.80
FRONT BUMPER FOGLAMP L/R <i>Replaced</i>	2	269.80	539.60
FRONT BUMPER LOWER GRILLE <i>Replaced</i>	1	497.10	497.10
FRONT BUMPER REINFORCEMENT <i>Replaced</i>	1	189.90	189.90
FRONT BUMPER SIDE RETAINER L/R <i>Replaced</i>	2	92.60	185.20
FRONT BUMPER SPONGE <i>Replaced</i>	1	149.60	149.60
FRONT BUMPER UNDER COVER <i>Replaced</i>	1	153.60	153.60

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

YAHYA BIN MOHAMED
BLK 475 SEMBAWANG DR #01-323
SINGAPORE 750475

Contact : 92309662

TAX INVOICE

Repair Code : CLM18371

Date in : 11/09/2024

Vehicle Num. : SMN4120H

Model : TOYOTA ESTIMA AERAS 2.4 A

Chassis/Eng# : ACR500056525/2AZF103526

FRONT GRILLE <i>cracked.</i>	1	869.20	869.20	✓
FRONT GRILLE OUTER CHROME COVER <i>new</i>	1	210.10	210.10	+
FRONT GRILLE TOP GARNISH <i>new</i>	1	186.50	186.50	+
FRONT HEADLAMP L/R <i>cracked</i>	2	2391.50	4,783.00	✓
FRONT HEADLAMP LOWER BRACKET L/R <i>new</i>	2	45.00	90.00	+
FRONT SUPPORT PANEL <i>Refr</i>	1	1810.70	1,810.70	+
RADIATOR (AUTO) <i>warpped</i>	1	3394.90	3,394.90	+
RADIATOR FAN BLADE	1	383.70	383.70	+
RADIATOR FAN COWLING	1	459.80	459.80	+
RADIATOR FAN MOTOR	1	892.90	892.90	+
RADIATOR LOWER HOSE	1	92.10	92.10	+
RADIATOR TOP BRACKET	1	156.50	156.50	+
RADIATOR TOP HOSE	1	113.20	113.20	+
REAR BLOWER MOTOR ASSY <i>Not new</i>	1	5775.20	5,775.20	+
REAR BUMPER <i>De lnd</i>	1	2102.90	2,102.90	880
REAR BUMPER CORNER RETAINER L/R <i>cracked</i>	2	78.70	157.40	✓
REAR BUMPER INNER SPONGE <i>cracked</i>	1	123.80	123.80	✓
REAR BUMPER RELFECTOR L/R <i>cracked</i>	2	69.80	139.60	✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

YAHYA BIN MOHAMED
 BLK 475 SEMBAWANG DR #01-323
 SINGAPORE 750475

TAX INVOICE

Repair Code : CLM18371

Date in : 11/09/2024

Vehicle Num. : SMN4120H

Model : TOYOTA ESTIMA AERAS 2.4 A

Chassis/Eng# : ACR500056525/2AZF103526

Contact : 92309662

REAR BUMPER SIDE RETAINER L/R	<i>Build</i>	2	59.70	119.40	✓
REAR BUMPER TOWING COVER L/R	<i>xle m</i>	2	39.40	78.80	X
REAR END PANEL	<i>Distorted</i>	1	1126.10	1,126.10	✓
REAR END PANEL INNER TOP GARNISH	<i>Delnd</i>	1	281.90	281.90	✓
REAR END PANEL LOWER GARNISH		1	301.80	301.80	✓
REAR EXHAUST RUBBER MOUNTING	<i>xle m</i>	2	57.80	115.60	+
REAR EXHAUST SILENCER BOX		1	981.30	981.30	+
REAR FENDER INNER TRIM BOARD L/R	<i>Delnd</i>	2	1299.40	2,598.80	✓
REAR FLOOR PANEL	<i>Repair</i>	1	1214.70	1,214.70	+
REAR FLOOR PANEL INNER TRIM GARNISH	<i>xle m</i>	1	417.90	417.90	+
REAR LH SEAT ASSY	<i>Not</i>	1	1002.60	1,002.60	+
REAR RH SEAT ASSY	<i>Not</i>	1	1063.40	1,063.40	+
REAR TAILGATE	<i>Dented</i>	1	3290.30	3,290.30	✓
REAR TAILGATE 'ESTIMA' EMBLEM		1	59.20	59.20	✓
REAR TAILGATE 'LOGO' EMBLEM	<i>xle m</i>	1	48.60	48.60	✓
REAR TAILGATE DAMPER L/R	<i>Not</i>	2	381.90	763.80	X
REAR TAILGATE GUIDE STOPPER L/R	<i>Not</i>	2	59.70	119.40	+
REAR TAILGATE HANDLE	<i>Not</i>	1	291.70	291.70	X

*** This is a computer-generated document which requires no signature.***

page 3

REAR FLOOR PANEL TOP BOARD COVER *725.00*
Delnd

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

YAHYA BIN MOHAMED
 BLK 475 SEMBAWANG DR #01-323
 SINGAPORE 750475

TAX INVOICE

Repair Code : CLM18371

Date in : 11/09/2024

Vehicle Num. : SMN4120H

Model : TOYOTA ESTIMA AERAS 2.4 A

Chassis/Eng# : ACR500056525/2AZF103526

Contact : 92309662

REAR TAILGATE HINGES L/R <i>Not m</i>	2	71.30	142.60	X
REAR TAILGATE INNER TRIM BOARD <i>cracked</i>	1	796.70	796.70	✓
REAR TAILGATE LOCK ACUATOR <i>Not m</i>	1	481.70	481.70	X
REAR TAILGATE MECHANISM LOCK <i>Done</i>	1	311.70	311.70	✓
REAR TAILGATE NUMBER PLATE LAMP L/R <i>Not m</i>	2	67.80	135.60	X
REAR TAILGATE OUTER GARNISH <i>cracked</i>	1	381.80	381.80	✓
REAR TAILGATE REFLECTOR LAMP (CENTER) <i>cracked</i>	1	301.80	301.80	✓
REAR TAILGATE REFLECTOR LAMP L/R <i>cracked</i>	2	281.70	563.40	✓
REAR TAILGATE WEATHER STRIP <i>lit</i>	1	211.90	211.90	✓
REAR TAILGATE WINDSCREEN MOULDING <i>New</i>	1	311.70	311.70	✓
REAR TAILLAMP L/R <i>cracked</i>	2	488.70	977.40	✓
Subtotal before discount			53,142.20	
Percentage discount 25%			13,285.55	
Sub-total 1			39,856.65	
FRONT BONNET INSUALTOR MAT CLIPS - SET <i>Not m</i>	1	30.00	30.00	X
FRONT BUMPER CLIPS - SET <i>New</i>	1	50.00	50.00	30
FRONT BUMPER UNDER COVER CLIPS - SET <i>Not m</i>	1	30.00	30.00	X
FRONT GRILLE CAMERA <i>Not m</i>	1	650.00	650.00	X

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

YAHYA BIN MOHAMED
BLK 475 SEMBAWANG DR #01-323
SINGAPORE 750475

Contact : 92309662

TAX INVOICE

Repair Code : CLM18371

Date in : 11/09/2024

Vehicle Num. : SMN4120H

Model : TOYOTA ESTIMA AERAS 2.4 A

Chassis/Eng# : ACR500056525/2AZF103526

FRONT GRILLE CLIPS - SET <i>New</i>	1	30.00	30.00 <i>10</i>
FRONT GRILLE TOP GARNISH CLIPS - SET <i>New</i>	1	30.00	30.00 <i>x</i>
FRONT NUMBER PLATE <i>Amold</i>	1	25.00	25.00 <i>✓</i>
FRONT NUMBER PLATE HOLDER <i>Defnd</i>	1	50.00	50.00 <i>30</i>
RADIATOR COOLANT <i>New</i>	1	80.00	80.00 <i>50</i>
REAR BUMPER CLIPS - SET <i>New</i>	1	30.00	30.00 <i>✓</i>
REAR BUMPER REVERSE SENSOR - SET <i>Defnd</i>	1	350.00	350.00 <i>300</i>
REAR FLOOR PANEL INNER TRIM GARNISH CLIPS - SET <i>New</i>	1	50.00	50.00 <i>x</i>
REAR LH FENDER INNER TRIM BOARD CLIPS - SET <i>New</i>	1	30.00	30.00 <i>✓</i>
REAR RH FENDER INNER TRIM BOARD CLIPS - SET <i>New</i>	1	30.00	30.00 <i>✓</i>
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>New</i>	1	30.00	30.00 <i>✓</i>
REAR TAILGATE NUMBER PLATE <i>Amold</i>	1	25.00	25.00 <i>✓</i>
REAR TAILGATE NUMBER PLATE GARNISH <i>Defnd</i>	1	50.00	50.00 <i>30</i>
REAR TAILGATE REVERSE CAMERA <i>New</i>	1	800.00	800.00 <i>x</i>
REAR TAILGATE WINDSCREEN SEALANT <i>New</i>	1	80.00	80.00 <i>60</i>
Subtotal before discount			2,450.00
Percentage discount 0%			0.00
Sub-total 2			2,450.00
Parts-total			42,306.65

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

YAHYA BIN MOHAMED
 BLK 475 SEMBAWANG DR #01-323
 SINGAPORE 750475

TAX INVOICE

Repair Code : CLM18371

Date in : 11/09/2024

Vehicle Num. : SMN4120H

Model : TOYOTA ESTIMA AERAS 2.4 A

Chassis/Eng# : ACR500056525/2AZF103526

Contact : 92309662

LABOUR

To remove, change air con parts, vacuums, refill air con gas.	150.00	120
To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)	80.00	30
To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	80.00	✓
To remove, reinstall tailgate windscreen	150.00	120
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	80.00	60
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	2,200.00	1400.
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	2,200.00	1400.
To apply anti-rust chemical on repaired and replaced panel.	80.00	60
To remove, reinstall tailgate mechanism and check for function	80.00	60
Labour Total	5,100.00	
Parts & Labour Total	47,406.65	

*** This is a computer-generated document which requires no signature.***

page 6

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Li
 11/09/24.
 11 Days.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	676G

Vehicle Details

Vehicle No.:	SMN4120H
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Sep 2024
Vehicle Make:	TOYOTA
Vehicle Model:	ESTIMA AERAS 2.4 A
Primary Colour:	Black
Manufacturing Year:	2007
Engine No.:	2AZF103526
Chassis No.:	ACR500056525
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$32,375.00
Original Registration Date:	21 Dec 2007
First Registration Date:	21 Dec 2007
Transfer Count:	1
Actual ARF Paid:	\$35,613.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	30 Nov 2027
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$50,168.00
COE Rebate Amount:	\$16,151.00
Total Rebate Amount:	\$16,151.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.
The information contained herein is correct as at 11 Sep 2024

OK