

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI24090197/EQP3M4
Date: 27/09/2024

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MZD01721		
Claimant Vehicle No :	SHC7225L	Insured Vehicle No :	YR1823U		
Date of Loss:	09/09/2024	Nature of Claim:	TP	Claim No:	M2405214

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC7225L		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDFU595958
Reg. Date:	11/08/2016 (Man. Year: 2016)	Chassis No:	KMHLB41UMGU092622
Colour:	Yellow	Odometer:	1231091 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	206/60R16	Rear Tyre Size:	206/60R16
Front Left Side:	Triangle 5 mm	Rear Left Side:	Triangle 5 mm
Front Right Side:	Triangle 5 mm	Rear Right Side:	Triangle 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	536.00	536.00	0.00	0.00
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	350.00	160.00	190.00	54.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	898.00	708.00	190.00	21.16
Approved Total (Overridden) (S\$)		550.00		
(S\$)	898.00	550.00	348.00	38.75
+ GST 9.00/9.00% (S\$)	80.82	49.50	31.32	38.75
Nett Amount (S\$)	978.82	599.50	379.32	38.75

INSPECTION

Date of Assignment:	10/09/2024	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	11/09/2024	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	1.0 days		

Adjuster: CHEN TSUE YEE Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Sep 2024)
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC7225L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR VIEW MIRROR RH	Broken	670.00 FL	*670.00 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$)					670.00	670.00
- List Item Discount on L Items 20.00/20.00% (\$)					134.00	134.00
Total Parts (\$)					536.00	536.00
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (\$\$)			12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	200.00	80.00
2	SPRAY PAINTING	New	150.00	80.00
Gross Labour Cost (\$\$)			350.00	160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >