



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)	Ref:	CS/SPF24090198/Rqp3m4
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE)	Date:	03/10/2024
POLICE LOGISTICS BASE (PLB)	Code:	SPF
1 HEMMANT ROAD SINGAPORE 438675		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 3157J	Veh. Inspected	SHD 8596D
Policy No.	-	Coverage	0
Claim No.	ACS/105/009/2024/046 (LK)	Excess	\$0.00
Assign From	LAI PENGCHONG	Assign Date	11/09/2024

### 2. Vehicle Details

Make & Model	HYUNDAI I40 1.7	C.C	1685
Engine No.	D4FDHU731303	Year of Reg.	15/09/2016
Chassis No.	KMHLB41UMGU093835	Colour	YELLOW
Odometer	792999 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: NIL		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/60R16	TRIANGLE	6
L/H Front Tyre	205/60R16	TRIANGLE	6
R/H Rear Tyre	205/60R16	TRIANGLE	6
L/H Rear Tyre	205/60R16	TRIANGLE	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	07/09/2024	Inspection Date	16/09/2024
Survey held at	31 CORPORATION ROAD – REPAIRER: DING AUTO PTE LTD		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days