

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24090199/KQP3E2
Date: 14/10/2024REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SNK8976H **Insured Vehicle No :** GBJ3136X

Date of Loss: 10/09/2024 Nature of Claim: TP Claim No: DMCV2400183H/02/AF

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNK8976H**

Make & Model: PEUGEOT 2008, 1.2 EAT8 ALLURE PREMIUM (A) Engine No: 10XVDW1964074

Reg. Date: 23/05/2023 (Man. Year: 2022) Chassis No: VR3USHNSSNJ758022

Colour: Metallic Grey Odometer: 10787 km

Engine Capacity: 1199 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17

Front Left Side: Continental 9 mm Rear Left Side: Continental 9 mm

Front Right Side: Continental 9 mm Rear Right Side: Continental 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,594.00	8,559.00	1,035.00	10.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,710.00	2,240.00	470.00	17.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,304.00	10,799.00	1,505.00	12.23
Approved Total (Overridden) (S\$)		10,000.00		
Nett Amount (S\$)	12,304.00	10,000.00	2,304.00	18.73

INSPECTION

Date of Assignment: 11/09/2024

Date Inspected: 11/09/2024 Inspected At: Rc Auto-160 Sin Ming (HQ)
160 SIN MING DRIVE, #06-20 SIN MING AUTOCITY
Singapore 575722

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Oct 2024)
Parts:	M1-SUV	PEUGEOT 2008 1.2 EAT8 ALLURE PREMIUM (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNK8976H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Dented	1,440.00 FL	*1,440.00 FL
2	1		*SET REAR BUMPER BRACKET L&R	Serviceable	190.00 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Bent	550.00 FL	*550.00 FL
4	1		*REAR BOOTLID	Bent	2,450.00 FL	*2,180.00 FL
5	1		*REAR LAMP	Cracked	640.00 FL	*640.00 FL
6	1		*REAR REFLECTOR	Cracked	420.00 FL	*420.00 FL
7	1		*REAR CORNER BUMPER BRACKET	Distorted	185.00 FL	*185.00 FL
8	1		*REAR BUMPER BRACKET - CENTRE INNER	Distorted	95.00 FL	*95.00 FL
9	1		*FENDER MOULDING	Necessary	285.00 FL	*285.00 FL
10	1		*REAR BUMPER LAMP	Cracked	265.00 FL	*265.00 FL
11	1		*REAR FENDER - L/H	Buckled	2,700.00 FL	*2,250.00 FL
12	1		*REAR BUMPER - CENTRE	Dented	1,440.00 FL	*1,200.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	10,660.00	9,510.00
- List Item Discount on L Items 10.00/10.00% (S\$)	1,066.00	951.00
Total Parts (S\$)	9,594.00	8,559.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING	New	1,200.00	1,000.00
2	TO RENEW ABOVE PARTS	New	1,200.00	1,000.00
3	TO REMOVE REAR WINDSCREEN	New	150.00	120.00
4	TO REMOVE UPHOLSTERY	New	120.00	100.00
5	TO CHECK WIRING	New	40.00	20.00
Gross Labour Cost (\$)			2,710.00	2,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >