

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Melvin Ye Yongkang

Date: 01 Jul 2024

Preliminary Advice

Insured Vehicle No	: SKC5085B	Accident Date	: 17/06/2024
TP Vehicle No	: SJV4356M	Assignment Date	: 20/06/2024
Make	: KIA CERATO FORTE	Est. Duration of Repair	: 3
Date of Inspection	: 25/06/2024		
Inspection At	: GALAXY AUTOCARE PTE LTD (HQ) 13 KAKI BUKIT ROAD 4 #01-23 BARTLEY BIZ CENTRE SINGAPORE 417807		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,795.20
Revised Amount	:S\$	2,511.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,511.50
 Lump Sum Repair	 :S\$	 2,000.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	6,000.00
COE / PARF Rebate	:S\$	1,922.00
Salvage Value	:S\$	
Margin for Repair	:S\$	4,078.00

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 (X) Lump Sum repair
- (X) The above survey was conducted on a 'without prejudice' basis.
 Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.