



Blk 416 Pasir Ris Dr 6 #08-235, Singapore 510416
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Muhammad Faris Bin Sulaiman
C/o: Black Industry Pte Ltd
25 Kaki Bukit Road 4
#01-43 Synergy@KB Singapore 417800

Date : 16 June 2023
Our ref : BIPL/06/2303/TP

Accident Date : 30 May 2023
Inspection Date : 6 June 2023
Repairer Name : Black Industry Pte Ltd
25 Kaki Bukit Road 4
#01-43 Synergy@KB Singapore 417800

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No : FBT 9383 G
Make / Model : Yamaha XSR155
Chassis No : MH3RG4760NK037150
Engine No : G3S7E0018185

Year / Capacity : 2022 / 155 cc
Colour : Blue
Mileage : 15632

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front	Pirelli	110/70 R17	5 mm	Sport
Rear	Pirelli	140/70 R17	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the front and n/s portion.
(Details refer to the photographs attached)

Enclosed number of photographs: 102 copies

REMARKS

This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$5,100.00** on a contractual basis.

Under normal circumstances, the repair period would be about 5 (Five) working days.

Vehicle Registration No.: FBT 9383 G

Our Ref No.: BIPL/06/2303/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Front fender assy	Damage	\$ 230.00	\$ 230.00
1	Front o/s fork assy	Intact	\$ 1,278.00	
1	Front n/s fork assy	Damage	\$ 1,278.00	\$ 1,278.00
1	Fork under bracket	Damage	\$ 650.00	\$ 650.00
1	Front sport rim	Damage	\$ 750.00	\$ 750.00
1	Front rim shaft	Necessary	\$ 65.00	\$ 65.00
1	Side mirror set	Damage	\$ 80.00	\$ 80.00
1	Headlamp	Damage	\$ 550.00	\$ 550.00
1	Handle bar	Damage	\$ 255.00	\$ 255.00
1	N/s handle bar balancer	Damage	\$ 45.00	\$ 45.00
1	Hand grip (1 set)	Necessary	\$ 70.00	\$ 70.00
1	Clutch lever	Damage	\$ 80.00	\$ 80.00
2	Fuel tank side covers	Damage	\$ 640.00	\$ 640.00
1	Fuel tank centre cover	Intact	\$ 255.00	
1	Side stand	Damage	\$ 75.00	\$ 75.00
1	Front n/s footrest	Damage	\$ 45.00	\$ 45.00
1	Front n/s footrest bracket	Damage	\$ 90.00	\$ 90.00
1	Gear pedal	Damage	\$ 75.00	\$ 75.00
1	Rear n/s footrest	Damage	\$ 55.00	\$ 55.00
1	Rear n/s footrest bracket	Damage	\$ 105.00	\$ 105.00
1	Radiator n/s side cover	Damage	\$ 110.00	\$ 110.00
1	Radiator tank	Intact	\$ 78.00	
			\$ 6,859.00	\$ 5,248.00
			<i>Less 10%</i>	<i>\$ 524.80</i>
Total Cost - List Items			\$ 6,173.10	\$ 4,723.20

SPECIAL NETT ITEMS

1	Front number plate	Damage	\$ 10.00	\$ 10.00
2	Fork oil	Necessary	\$ 40.00	\$ 40.00
2	Fork oil seals	Necessary	\$ 70.00	\$ 70.00
1	ERP IU	Damage	\$ 175.00	\$ 175.00
1	Rear box	Damage	\$ 700.00	\$ 700.00
1	Rear box bracket	Damage	\$ 120.00	\$ 120.00
1	Headlamp grille	Damage	\$ 80.00	\$ 80.00
Total Cost - Special Nett items			\$ 1,195.00	\$ 1,195.00

Total cost of parts	\$ 7,368.10	\$ 5,918.20
----------------------------	--------------------	--------------------

Vehicle Registration No.: FBT 9383 G

Our Ref No.: BIPL/06/2303/TP

S/No	Description	Repairer's Estimate	Revised Amount
Total cost of parts c/f		\$ 7,368.10	\$ 5,918.20
<u>LABOUR</u>			
1	To provide towing service.	\$ 50.00	\$ 50.00
2	To check electrical system, wire harness and focus headlamp.	\$ 80.00	\$ 50.00
3	To provide labour charges, workmanship to dismantle above damaged parts ; re-align body structure and damaged consistent to the accident.	\$ 450.00	\$ 400.00
GRAND TOTAL		\$ 7,948.10	\$ 6,418.20



C L APPRAISER PTE LTD

Vehicle Registration No.: FBT 9383 G

Our Ref No.:

BIPL/06/2303/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 5,100.00**

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.


Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Disclaimer


The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD

Cheong K. H
Automotive Appraiser



APR 28 1988
FBI











BLACKINDUSTRY
APPRAISER
1738









PTC LTD













9383G






























Black Industry Pte Ltd

25 Kaki Bukit Road 4, #01-43 Synergy@KB Singapore 417800

REG NO: 202014052W

Tel : 6980 6315 HP : 8468 1738

Owner : Muhammad Faris Bin Sulaiman
Address : c/o :Black Industry Pte Ltd
25 Kaki Bukit Road 4
#01-43 Synergy@KB Singapore 417800

Date : 16-Jun-23

Model : Yamaha XSR155
File No. : FBT 9383 G

D.O.A : 30-May-23

ITEM NO	DESCRIPTION		U.PRICE SGD	AMOUNT SGD
1	LUMP SUM REPAIR COST AS PER SURVEYOR REPORT RECOMMENDATION		SGD 5,100.00	SGD 5,100.00
Grand Total:				SGD 5,100.00