



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS TAN CHIN HOE & CO		Ref:		CS/LAW24090208/Dnp3m4
70 SHENTON WAY, #12-10, EON SHENTON SINGAPORE		Date:		07/11/2024
079118		Code:		L128
1. Policy Particulars :- THIRD PARTY CLAIM (PHYSICAL REINSPECTION)				
Insured Veh.	SLK 1243J	Veh. Inspected	FBT 9383G	
Policy No.	-	Coverage	0	
Claim No.	RT/JR/5/2024/JO	Excess	\$0.00	
Assign From	JEAN ONG	Assign Date	11/09/2024	
2. Vehicle Details				
Make & Model	YAMAHA XSR155	C.C	155	
Engine No.	G3S7E0018185	Year of Reg.	2022	
Chassis No.	MH3RG4760NK037150	Colour	BLUE	
Odometer	38864 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	110/70R17	PIRELLI	2	
L/H Front Tyre				
R/H Rear Tyre	140/70R17	PIRELLI	2	
L/H Rear Tyre				
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	30/05/2023	Inspection Date	30/09/2024	
Survey held at	BLACK INDUSTRY PTE LTD - 25 KAKI BUKIT ROAD 4 #01-43 SYNERGY @ KB, SINGAPORE 417800			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				