

FormTeam Consultancy Pte Ltd

No.52, Ubi Ave 3
#05-46, Frontier
Singapore 408867

Tel : (65) 6509 1788
Fax : (65) 6509 6221

Email: motorsurvey@fta.com.sg

Co.Reg No: 200819280D

GST Reg No: 200819280D

Our Reference : NTUC23-064273/PRS/YH/ADJ/YH/cg

Your Reference: MT/1226212-001

Date : 04-Aug-2023

Motor Claims Department
Income Insurance Limited
75 Bras Basah Road
Income Centre
Singapore 189557

Attention : Mr Marcus Xiao

Dear Sir/Mdm,

SURVEY OF VEHICLE NO. FBT 9383G

Pursuant to your instruction on **02-Aug-2023**.

We recommend a repair cost of **\$2,550.00** (see report) based on lump sum repair and the estimated duration of repairs would take **03 days**.

Thank you for this assignment.

Your faithfully

FormTeam Consultancy Pte Ltd
Adjusters & Surveyors (Licensed Appraiser)



Ng You Han
Automobile Appraiser

(Email : yhng@fta.com.sg)

Encl. Survey Report

FormTeam Consultancy Pte Ltd

AUTOMOBILE ASSESSMENT REPORT

Page No. 1

Our Reference : NTUC23-064273/PRS/YH/ADJ/YH/cg

Your Reference: MT/1226212-001

Date : 4-Aug-2023

Attention : Mr Marcus Xiao

TO : Motor Claims Department
Income Insurance Limited
75 Bras Basah Road
Income Centre
Singapore 189557

Assessment of Vehicle No : **FBT 9383G**
Date of Accident : **30-May-2023**
Date of Inspection : **07-June-2023**
Address of Inspection : **25 Kaki Bukit Road 4 #01-43 Synergy S'417800**

We have carried out a physical assessment of **FBT 9383G** at **M/S Black Industry Pte Ltd** according to your instructions on **07-Jun-2023**, dismantled items on **08-Jun-2023**, post repair survey on **09-Jun-2023** and are pleased to submit our report herewith.

1. VEHICLE PARTICULARS

Registration No. : FBT 9383G
Make & Model : Yamaha XSR155
Year of Registration : 2022
Engine Capacity : 155 cc
Chassis No. : MH3RG4760NK037150
Engine No. : G3S7E0018185
Colour : Blue
Mileage (km) : 15632

2. VEHICLE CONDITION

Body Paint : Fair
Steering : Serviceable
Foot Brake : Serviceable
Parking Brake : Nil

3. TYRE PARTICULARS & CONDITION

Front

RH Make/Size : Pirelli 110/70 R17 - 50%
LH Make/Size :

Rear

RH Make/Size : Pirelli 140/70 R17 - 50%
LH Make/Size :

Note : % denotes the remaining percentage of the tyre


FormTeam Consultancy Pte Ltd

Our Reference : NTUC23-064273/PRS/YH/ADJ/YH/cg
Your Reference : MT/1226212-001
Vehicle Number : FBT 9383G

Page No. 2

4. DESCRIPTION OF DAMAGE

At the time of inspection, this vehicle sustained damages to the **LHS** portion. Please see attached scheduled for details.



5. REMARKS

Market Value : -
Salvage Value : -
Repair Limit (Nett Loss) : -
Repairer's estimate : **Not Provided**
Nett Saving : -
Excess : -
Sum Insured : -
Our adjusted amount : **\$ 2,550.00**
Estimated Repair Days : **03 days**

Additional photographs will be submitted upon request by our principal.

Pursuant to your instruction, we have **NOT AUTHORIZED** repair.

The assessment was conducted on a "**Without Prejudice**" basis.

If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by

FormTeam Consultancy Pte Ltd for any reliance on this report by any third party, unless with the permission of the addressee.

FormTeam Consultancy Pte Ltd

Our Reference : NTUC23-064273/PRS/YH/ADJ/YH/cg
Your Reference : MT/1226212-001
Vehicle Number : FBT 9383G

Page No. 3

[illegible]

FormTeam Consultancy Pte Ltd

Our Reference : NTUC23-064273/PRS/YH/ADJ/YH/cg
 Your Reference : MT/1226212-001
 Vehicle Number : FBT 9383G

Page No. 4

| QTY | DESCRIPTION | CONDITION | REPAIRER'S ESTIMATE (S\$) | OUR ASSESSMENT (S\$) |
|-----|----------------------------------|-----------------------------|------------------------------|----------------------------|
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | Front Number Plate | Bent | - | 10.00 |
| 2 | Fork Oil | Necessary | - | 40.00 |
| 2 | Fork Oil Seals | Necessary | - | 50.00 |
| 1 | ERP IU | Cut | - | 175.00 |
| 1 | Rear Box | Cut | - | 450.00 |
| 1 | Rear Box Bracket | Serviceable | - | - |
| 1 | Headlamp Grille | Damaged | - | 60.00 |
| | | Special Nett Total : | - | 785.00 |
| | | Parts Total : | - | 2,880.20 |

FormTeam Consultancy Pte Ltd

Our Reference : NTUC23-064273/PRS/YH/ADJ/YH/cg
Your Reference : MT/1226212-001
Vehicle Number : FBT 9383G

Page No. 5

| S/N | DESCRIPTION | REPAIRER'S ESTIMATE (S\$) | OUR ASSESSMENT (S\$) |
|-----|--|------------------------------|-------------------------|
| | LABOUR | | |
| 1 | To provide towing service. (LOD Direct to Insurance) | - | - |
| 2 | To remove and refix damaged parts, align and renew replaced parts. | - | 300.00 |
| | Labour Total : | - | 300.00 |
| | TOTAL (PARTS & LABOUR) : | - | 3,180.20 |

The final adjusted Lump Sum contract amount is \$ **2,550.00**
(SINGAPORE DOLLARS TWO THOUSAND FIVE HUNDRED AND FIFTY ONLY)



Frankie Pang
AMSAE(AUST), AMIRTE, AMSOE,
MASPACI, MSAAA
Licensed Appraiser



Ng You Han
Automobile Appraiser