

08/11/13 Wef

ASS. REC. BY:

REF: CS/FCI 24090212/Rnp3

2921

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMH 3523S
at Workshop m/s ARC
of TOH GUAN RD 2001
Insured: FCI

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 73K

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: SMH 3523S Yr Regn: 2019 / JAN
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: SUZUKI VITARA 1.6 GLX c.c 1586

Colour: ORANGE AC: Insured / Std / NI / NA

Sp. Reading: 101957 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JSMLYD21500441878

Gen. Cond: Good (Fair) / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI (S/Rim) / STD A/Rim or

Tyre Size: F: 215/55R17

R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (PIR) / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 10/09/24

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - SIK

We will be advising our principal a cost of repair L/S \$3,600.00 /- with 06 days of repair (red, \$5902, 62%)

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

1)

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

) \$ + RS \$ _____

) Photos

) Others

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

TOTAL

☐



Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C

Estimate

48 Toh Guan Rd East Enterprise Hub
#02-143/144/145/146/147, Singapore 608586
Tel: 89183288 Fax: 67228585
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2409-593-TG
DATE : 10-Sep-2024
VEHICLE REG. NO. : SMH3523S
VEHICLE MAKE : SUZUKI / VITARA 1.6 GLX
CHASSIS : TSMLYD21S00441878
COE EXPIRY : 21-Jan-2019

TO First Cap

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	Qty	UNIT LIST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Rear Bumper <i>de</i>	1	\$ 1,000.00	\$ 1,000.00
2	Rear Bumper Side Retainer LH <i>X</i>	1	\$ 40.00	\$ 40.00
3	Rear Bumper Side Retainer RH <i>X</i>	1	\$ 40.00	\$ 40.00
4	Rear Bumper Reflector LH <i>X</i>	1	\$ 40.00	\$ 40.00
5	Rear Bumper Reflector RH <i>X</i>	1	\$ 40.00	\$ 40.00
6	Rear Bumper Lower <i>de X</i>	1		\$ -
7	Rear Bumper Diffuser Cover <i>de</i>	1	\$ 400.00	\$ 400.00
8	Rear Bumper Reinforcement <i>BT</i>	1	\$ 890.00	\$ 890.00
9	Rear End Panel <i>de</i>	1	\$ 520.00	\$ 520.00
10	Rear End Panel Top Garnish <i>de</i>	1	\$ 200.00	\$ 200.00
11	Rear End Panel Top Garnish RH <i>X</i>	1	\$ 170.00	\$ 170.00
12	Rear End Panel Top Garnish LH <i>X</i>	1	\$ 170.00	\$ 170.00
13	Tail Lamp RH <i>X</i>	1	\$ 500.00	\$ 500.00
14	Tail Lamp LH <i>X</i>	1	\$ 500.00	\$ 500.00
15	Tailgate <i>de</i>	1	\$ 1,050.00	\$ 1,050.00
16	Tailgate Emblem Suzuki <i>new</i>	1	\$ 40.00	\$ 40.00
17	Tailgate Emblem S <i>X</i>	1	\$ 30.00	\$ 30.00
18	Tailgate Emblem Vitara <i>new</i>	1	\$ 40.00	\$ 40.00
19	Tailgate Weatherseal <i>de</i>	1	\$ 170.00	\$ 170.00
20	Tailgate Lock <i>X</i>	1	\$ 200.00	\$ 200.00
21	Tailgate Striker <i>X</i>	1	\$ 40.00	\$ 40.00
22	Tailgate Inner Trim <i>X</i>	1	\$ 400.00	\$ 400.00
23	Rear Windscreen Moulding <i>new</i>	1		\$ -
24	Rear Floor Board <i>X</i>	1	\$ 630.00	\$ 630.00
25	Rear Floor Panel <i>X</i>	1	\$ 350.00	\$ 350.00
26	Tailgate Lamp RH <i>X</i>	1	\$ 390.00	\$ 390.00
27	Tailgate Lamp LH <i>X</i>	1	\$ 390.00	\$ 390.00
Total Cost Less 20%				\$ (1,648.00)
Total Spare Parts				\$ 6,592.00

48 Toh Guan Rd East Enterprise Hub
#02-143/144/145/146/147, Singapore 608586
Tel: 89183288 Fax: 67228585
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2409-593-TG
DATE : 10-Sep-2024
VEHICLE REG. NO. : SMH35235
VEHICLE MAKE : SUZUKI / VITARA 1.6 GLX
CHASSIS : TSMLYD21S00441878
COE EXPIRY : 21-Jan-2019

TO First Cap

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	Qty	UNIT LIST	TOTAL COST
	SPECIAL NETT			
28	Rear Number Plate w Casing <i>sum</i>	1	\$ 40.00	\$ 35 40.00
29	Reverse Sensor <i>X</i>	1	\$ 280.00	\$ 280.00
30	Rear Windscreen Sealant <i>W</i>	1	\$ 40.00	\$ 40.00
31	Clips - Rear Bumper, Tailgate Inner Trim <i>W</i>	20	\$ 3.00	\$ 60.00
Total Special Nett				\$ 420.00
	LABOUR			
32	Remove, Refit, Replace and Repair Affected Area	1	\$ 1,000.00	\$ 600 1,000.00
33	Spray painting (Whole Rear, End Panel)	1	\$ 1,000.00	\$ 600 1,000.00
34	Remove and Refit Rear Windscreen	1	\$ 150.00	\$ 120 150.00
35	Remove and Refit Reverse Sensors	1	\$ 80.00	\$ 60 80.00
36	Rust Proofing	1	\$ 80.00	\$ 60 80.00
37	Diagnose, Rectify Faults	1	\$ 150.00	\$ 100 150.00
38	Check and Rectify Wiring	1	\$ 30.00	\$ 20 30.00
Total Labour				\$ 2,490.00
Amount				\$ 9,502.00
Add GST @ 8%				760.16
Total Amount Payable				\$ 10,262.16

Estimate prepared by: RAZALI

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Paul
H99010068
6 days
4/5
30/09/24
Reg after
rep

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	292I
Vehicle Details	
Vehicle No.:	SMH3523S
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Oct 2024
Vehicle Make:	SUZUKI
Vehicle Model:	VITARA 1.6 GLX 6AT 2WD
Primary Colour:	Orange
Manufacturing Year:	2017
Engine No.:	M16A2217651
Chassis No.:	TSMLYD21S00441878
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$15,502.00
Original Registration Date:	21 Jan 2019
First Registration Date:	21 Jan 2019
Transfer Count:	0
Actual ARF Paid:	\$15,502.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Jan 2029
PARF Rebate Amount:	\$10,851.00
Intended COE Rebate Details	
COE Expiry Date:	20 Jan 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$25,920.00
COE Rebate Amount:	\$11,148.00
Total Rebate Amount:	\$21,999.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 01 Oct 2024

OK



Suzuki Vitara 1.6A GLX Sunroof

\$71,800 Instalment \$1,151/mth

PREMIUM AD

Apply for 2.48% loan

Shortlist

Get Warranty



- Overview
- Financial
- Photo
- Research

Depreciation	<i>i</i> \$15,390 / year
Reg. Date	14-Nov-2018 (4yrs 1mth 13days COE left)
Manufactured	<i>i</i> 2017
Mileage	44,500 km (7.6k / year)
Transmission	Auto
Engine Cap	1,586 cc
Road Tax	<i>i</i> \$736 / year
Power	88.0 kW (118 bhp)
Curb Weight	<i>i</i> 1,240 kg
COE	<i>i</i> \$28,199
OMV	<i>i</i> \$16,779
APF	<i>i</i> \$16,779