

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No. 08102600F

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SNG321X

No.	Qty	List Items	
1	1	Front bumper	Budget \$ 1,485.50 ✓
2	1	Front bumper RH parking sensor	\$ Cur 256.80 ✓
3	1	Front bumper RH fog lamp cover	\$ Sn 89.00 X
4	1	Front bumper RH fog lamp	\$ Cur 315.15 ✓
5	1	Front bumper RH headlamp washer nozzle	\$ Sn 201.50 X
6	1	Front bumper RH side retainer	\$ Sn 33.80 X
7	1	Rear bumper inner foam	\$ Sn 118.00 X
8	1	Rear bumper inner reinforcement	\$ Sn 843.95 ✓
9	1	Rear bumper inner parts	\$ Sn 210.95 X
10	1	RH headlamp	\$ Cur 2,896.40 ✓
			\$ 6,451.05
Less 5%			\$ 322.55
Total :			\$ 6,128.50

	Labour	
1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$ 500.00 250l
2	To putty and spray Spray Paintings charges.	\$ 500.00 250l
3	To check wirings and lightings.	\$ 40.00 20l
4	To remove, refit & reset front bumper parking sensors.	\$ 80.00 60l
5	To supply and apply anti rust treatment	\$ 30.00 X
Total :		\$ 1,150.00

Total Parts and Labour : \$ 7,278.50

Not Notched
 11 Pm @ 485d/r
 Return After Paint
 3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: