

辉 陽 汽 車 有 限 公 司 HUI YANG MOTOR PTE. LTD.

AIG
10/9/2024

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST & Reg No. 201629438M

NOT Authorized
1/1ump @ 3100p
Per survey After Paint
4 days

03/09/2024

Owner: LIM HUNG TONG

ESTIMATE TO REPAIR HONDA SHUTTLE - SMR1270G

1pc	rear tailgate		M \$ 1,193.70	✓
1pc	rear tailgate "H" logo		M \$ 58.00	✓
1pc	rear tailgate "SHUTTLE" emblem		M \$ 55.00	✓
1pc	rear tailgate outer garnish		P \$ 480.50	X
1pc	rear tailgate RH reflector		P \$ 380.20	X
1pc	rear tailgate windscreen moulding <i>121-60</i>		M \$ 195.00	✓
1pc	rear tailgate inner rubber		Dd Dis \$ 188.50	✓
1pc	rear tailgate inner lock		S \$ 385.20	X
1pc	rear RH taillamp		S \$ 581.50	X
1pc	rear bumper <i>936</i>		M \$ 1,150.60	✓
1pc	rear bumper centre chrome <i>166</i>		M \$ 195.50	✓
1pc	rear bumper RH side reflector		P \$ 125.50	X
1pc	rear bumper RH side retainer		P \$ 58.20	X
10pcs	rear bumper clip @\$5.00		M \$ 50.00	✓
1pc	rear end panel		R \$ 685.00	X
1pc	rear end panel inner garnish <i>186-60</i>		Mj Dis \$ 285.50	✓

\$ 6,067.90
\$ 1,213.58
\$ 4,854.32

1set	rear parking sensor		Dd/Shop s.nett \$ 280.00	<i>200sn</i>
1set	rear number plate & casing		s.nett \$ 50.00	X

remove & refit rear windscreen glass		\$ 120.00	✓
sealant		\$ 80.00	<i>40sn</i>
wiring		\$ 100.00	<i>201</i>
tuffkote		\$ 100.00	<i>301</i>
spray painting		\$ 1,000.00	<i>60d</i>
labour charges		\$ 1,000.00	<i>50d</i>
Total		\$ 7,584.32	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved and is subject to final approval from insurance company

Acknowledged by Repairer
Signature: _____
Date: _____