

ESTIMATION QUOTE

CHASSIS : W1K1183542N158997

ATTN : MOTOR CLAIMS DEPARTMENT

VEHICLE NO : SME 69Y
MAKE MODEL : MERCEDES CLA 45S
REFERENCE :
DOA : 11.09.2024
CLAIM TYPE : THIRD PARTY CLAIM

PARTS	QTY	LIST PRICE (\$)	
HEADLAMP LH / BR / CWI	1	\$ 4,370.00	-3424 / 4091.21 /
HEADLAMP BRACKET LH X nn	1	\$ 280.00	
FRONT BUMPER / BR / DLF	1	\$ 2,800.00	-1566 / 2272.40 /
FRONT BUMPER BRACKET LH X nn	1	\$ 180.00	
FRONT BUMPER BRACKET RH X nn	1	\$ 180.00	
FRONT BUMPER SIDE RETAINER LH X nn	1	\$ 40.00	
FRONT BUMPER SIDE RETAINER RH X nn	1	\$ 40.00	
FRONT BUMPER GRILLE X nn	1	\$ 420.00	
AIR VENT COVER X BR (Fog lamp LH)	1	\$ 142.00	/
BUMPER SPONGE / BR	1	\$ 250.00	162 /
FOGLAMP MOULDING / (07)	1	\$ 450.00	352 /
		\$ 9,152.00	
	LESS 5%	\$ 457.60	
	TOTAL	\$ 8,694.40	

7019.61
-5%
6668.62

SPECIAL NETT ITEMS	QTY	LIST PRICE (\$)	REMARKS
FRONT BUMPER SENSOR / Shorted (1pc)	1 SET	\$ 960.00	240 /
FRONT BUMPER RADAR SENSOR X nn	1 SET	\$ 2,980.00	
FRONT LIP (CARBON FIBER) / BR	1	\$ 1,600.00	-500 600 /
SIDE LIP (CARBON FIBER) / BR (LH) X nn	1	\$ 1,700.00	300
AIR VENT (CARBON FIBER) / BR (Fog lamp LH)	1	\$ 850.00	-300 650 /
FRONT CANNARD (CARBON FIBER) X nn	1	\$ 950.00	
WRAP / n/c	1	\$ 1,200.00	400 /
		\$ 10,240.00	

1890

LABOUR	LIST PRICE (\$)	REMARKS
BALANCE B/F	\$ 18,934.40	
CHECK REAR WIRING AND LIGHTING SYSTEM	\$ 500.00	80
REMOVE AND RENEW SENSOR	\$ 350.00	50
DIAGNOIS CHECK AND CLEAR FAULT CODE	\$ 400.00	80
TRANSFER PARTS, ATTACHMENT FROM OLD REAR TO NEW	\$ 500.00	X
REMOVE AND REINSTALL THE WRAP	\$ 1,200.00	150
PANEL BEATING ON AFFECTED AREAS AND RENEW PART	\$ 800.00	300
SPRAY PAINTING ON AFFECTED AREAS	\$ 800.00	250
SUBTOTAL	\$ 4,550.00	
GRAND TOTAL	\$ 23,484.40	

910

Steve (LKK)
13/9/24, 10.00 am
m R
L/S
H H H
4-3-4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

9468.62

L/S - 7574.89
= 7550