



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

Not Authorized

1 October 2024

REG NO.: SLU 7440 P
MAKE/MODEL: NISSAN QASHQAI

12/9/24
2/5 \$8000
the ph. After 10p. 6 days.

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>NETT ITEMS</u>	
1	Front bonnet	\$ R 1,054.30 X
1	Front bonnet lock	\$ 11 55.90 X
1	Front bonnet rubber	\$ 11 77.70 X
1	Front headlamp RH	\$ ONE 2,617.00 ✓
1	Front fog lamp RH t	\$ ONE 386.10 ✓
1	Front grille assy	\$ 11 322.40 X
1	Front grille logo	\$ 11 58.40 X
1	Front bumper	\$ 10/7-10 1,855.00 ✓
1	Front bumper lower grille	\$ 11 320.00 X
1	Front bumper reinforcement-top	\$ 11 591.90 X
1	Front bumper reinforcement-bottom	\$ 11 183.50 X
2	Front bumper side retainers	\$ 27.30 M/S 54.60 PC
1	Front bumper side moulding	\$ 11 138.00 X
1	Front bumper side grille o/s	\$ 11 145.00 ✓
1	Front bumper undercover	\$ 11 246.70 X
1	Front bumper sponge-top	\$ 11 207.00 X
1	Front bumper sponge-bottom	\$ 11 207.00 X
1	Front fender -RH	\$ 3UC 622.70 ✓
1	Front fender inner shield	\$ 7.11 83.60 ✓
1	Front fender arch garnish	\$ DIS 541.40 ✓
1	Front support panel	\$ R 682.70 X
1	Front support side garnish	\$ 11 90.40 X
1	Wiper tank with motor	\$ 5UC 168.50 X
1	Front wheel hub with bearing o/s	\$ 11 467.00 ✓
1	Front shock absorber o/s	\$ 5UC 453.20 ✓
1	Front knuckle arm o/s	\$ 5UC 676.70 ✓
1	Front lower arm o/s	\$ 5UC 248.60 ✓
1	Front anti roll bar	\$ 5UC 241.50 ✓
1	Front anti roll bar link	\$ 11 69.10 ✓
1	Steering rack assv	\$ 5UC 1,325.80 X
1	Front Engine cross member	\$ 5UC/11 1,017.70 ✓
1	Front brake ABS sensor -RH o/s	\$ 11 182.60 X
1	Front door -RH o/s	\$ R 1,523.50 X
1	Front door rubber	\$ 11 182.20 X
1	Front door side mirror	\$ 11 386.50 X
1	Front door outer lower garnish	\$ 11 284.80 X
		\$
	Less 10%	\$
		\$

SPECIAL NETT ITEMS

- 1 Front bumper clip (1 set)
 1 Front bumper fog lamp
 1 Front fender inner shield clip (1 set)
 1 Front tyre
 1 Front sport rim -RH

\$	nu	80.00	40 S/N
\$	Repub	279.20	X
\$	nu	38.00	30 S/N
\$	SU	450.00	X
\$	unpub	950.00	400 S/N
\$		1,797.20	

S/N**LABOUR CHARGES**

- 1 To check wiring and reset headlamps focusing.
 2 To remove and refit front undercarriage.
 3 To conduct wheel alignment.
 4 To remove, refit door fittings and replace damaged parts, transfer all fittings to new door.
 5 To apply undercoating.
 6 Panel beating.
 7 To re-spray painting on the affected areas.

\$		80.00	20
\$		450.00	300
\$		180.00	60
\$	11	150.00	X
\$		180.00	30
\$		1,800.00	550
\$		1,600.00	900
\$		4,440.00	

GRAND TOTAL :**\$**

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-8614
 102
 7752.60
 470
 1860
 10082.60
 203
 8000