

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0681/2024/KS
DATE : 13-Sep-24
WIP : 30696

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 17/9/2024

YOUR INSURED VEH NO : SNK 8754 G

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR. BEK AIK PING ANDY MAI YIBIN ANDY)
ADDRESS : 101 WEST COAST VALE
#09-06
SINGAPORE 126753
TELEPHONE : HP +65 91149756
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2070150198-03
VEHICLE NO : SMV 9206 U
MODEL CODE : A5 SPORTBACK 2.0 TFSI
MODEL YEAR : 27/10/2020
ENGINE NO : DEM 025629
CHASSIS NO : WAUZZZF51MA003541
MILEAGE : KM
DATE IN :
ESTIMATED BY : JOE WNY BOO / ALLAN WU
ACCIDENT DATE : 12-Sep-24
PLACE OF ACCIDENT : W COAST RD, SINGAPORE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SMV 9206 U.

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$	360.00	/
2	TO REMOVE AND REINSTALL REAR BUMPER. TO REPAIR RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,750.00	500
3	TO RESPRAY REAR BUMPER AND RHS REAR FENDER.	\$	1,800.00	1190
4	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	292.00	/
5	TO RE-APPLY PAINT COATING AND PPF ON AFFECTED AREA (Refer quotation)	\$	570.00	/
TOTAL LABOUR CHARGES		:	\$ 4,772.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 9206 U.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER X R	1	\$ 2,945.00	
2	REAR BUMPER GUIDE SECTION - RH X nn	1	\$ 56.00	
3	REAR BUMPER GUIDE SECTION - RH X nn	1	\$ 29.00	
4	SUNDRIES ? x nn		\$ 150.00	
TOTAL SPARE PARTS		:	\$ 3,180.00	
TOTAL LABOUR CHARGES		:	\$ 4,772.00	
GRAND TOTAL		:	\$ 7,952.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Steve (LKK)
17/9/24, 10.30am
with Mr. [unclear]

P/P, My Bel sy, (4 + 1 coating)
Days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT



Quotation

TERM:

DESCRIPTION	AMOUNT
Quotation for re-application of Ceramic Coating & PPF :	
Area Include : Rear Bumper + Full Right Hand Side panel	\$ 480.00
PPF Area : Rear Boot Ledge PPF	\$ 90.00
Re-application Process consist of decontamination wash and preparation of surface, re-application of affected Area.	
	\$ 570.00

ADD: 7 Soon Lee Street #01-26 ISPACE Singapore 627608 | T:+65 6254 0456 | E:info@5dsolutions.com.sg