

利民达摩多



Jementah Motor Works

Blk 14 Defu Lane 10 #01-406

Singapore 539195

H/P : 9299 6636 Fax : 6285 7054

*W, f Authorised
no
meras
13/9/24
1/5 #4300
4 days
Zhang, Attorney*

Date : 12-Sep-24

Estimated repair cost of SMU 871 M BMW 216i

<u>Qty</u>	<u>Description</u>		<u>Amt S(\$)</u>
	<u>List Items</u>		
1	Rear windscreen inner seal <i>neu</i>		\$ 95.00 ✓
1	Rear tailgate <i>DP/3014</i>	1574.60	\$ 1,850.00 ✓
2	Rear tailgate dampers <i>11</i>		\$ 707.80 X
1	Rear tailgate inner board <i>11</i>		\$ 381.25 X
2	Rear tailgate lamps <i>o/s scu</i>	212.25	\$ 511.30 <i>lpc</i>
1	Rear tailgate lock <i>11</i>		\$ 193.80 X
1	Rear tailgate logo <i>neu</i>		\$ 71.25 ✓
1	Rear tailgate rubber <i>11</i>		\$ 143.00 X
1	Rear tailgate "216i" emblem <i>neu</i>	60.00	\$ 88.00 ✓
2	Rear taillamps <i>o/s scu</i>	303.20	\$ 845.20 <i>lpc</i>
1	Rear end panel <i>12</i>		\$ 635.20 X
1	Rear end panel inner garnish <i>11</i>		\$ 179.15 X
1	Rear bumper <i>7011</i>	1132.40	\$ 1,245.45 ✓
1	Rear bumper inner frame garnish <i>010</i>		\$ 122.70 ✓
1	Rear bumper lower diffuser <i>12</i>		\$ 471.00 X
2	Rear bumper reflectors <i>11</i>		\$ 77.40 X
1	Rear bumper reinforcement <i>DIS</i>		\$ 458.10 ✓
2	Rear bumper side retainers <i>11</i>		\$ 122.70 X
1	Rear tow hook cover <i>11</i>	28.00	\$ 65.00 ✓
2	Rear bumper PDC sensors <i>52C</i>		\$ 497.40 X
1	Control module for park assistant kit <i>11</i>		\$ 526.10 X
1	Park assistant kit support bracket <i>11</i>		\$ 185.00 ✓
			\$ 9,471.80
	Less 5%		\$ 473.59
			\$ 8,998.21

Special Nett Items

1	Rear windscreen sealant	<i>nee</i>	\$	80.00	<i>40</i>
1	Rear bumper clip (1 set)	<i>nee</i>	\$	60.00	<i>30</i>
			\$	<u>140.00</u>	

S/N LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.		\$	80.00	<i>20</i>
2	To remove and refit inner garnishes.		\$	<i>11</i> 150.00	<i>X</i>
3	To remove and refit rear reverse sensor.		\$	120.00	<i>30</i>
4	To transfer rear tailgate mechanism and wiring assembly.		\$	80.00	<i>50</i>
5	To remove and refit rear windscreen glass.		\$	180.00	<i>120</i>
6	To apply undercoating.		\$	150.00	<i>30</i>
7	Panel beating.		\$	1,600.00	<i>440</i>
8	To re-spray painting on the affected areas.		\$	<u>1,500.00</u>	<i>600</i>
			\$	<u>3,860.00</u>	

Grand Total : \$ 12,998.21

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 42425
52
4030.38
70
1290
5390.38
200
4312