

FC2

# 来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267  
GST No: M2-0128609-3  
UEN: 199407592C

## ESTIMATE

EST. No ..... EST0035708  
Wong Kaijie, Allan (Huang Kaijie,  
Allan)

Page ..... 1 of 1  
Your ref. .... TP-SHC 504C MS FC  
Job No. .... 74704  
Our ref. .... 24.09.11  
Payment .....  
Date ..... 12/9/2024

Attn .....

Vehicle No .... SMA 7193X  
Vehicle Model : Toyota C-HR  
Accident on ... 10/9/2024

*Not Authorised*  
*Running After Repair*  
*2 days*

811.33

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Rear bumper centre garnish	575.10	25.00 <i>Red 1/1</i>	431.33 ✓
Labour & Misc:					
1.00		To remove rear bumper in order to renew above part	200.00		200.00 ✓
1.00		To remove/refit/respray rear bumper diffuser (x2) after market	200.00		200.00 <i>1801</i>

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Sub-Total	831.33
GST 9.00%	74.82
Total	906.15

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。  
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."