ESTIMATED ACCIDENT REPAIR COST



Co. / GST Reg No. 201419417K

ACCIDENT TIME REPORTED	14:47 HRS	
ACCIDENT DATE	17-Jun-24	
BUS CAPTAIN NAME	TOH JIA HAUR	
THIRD PARTY CLAIM AGAINST	SMRT	

BUS REGISTRATION NUMBER	SG6367R	
BUS TYPE (SD/DD)	DD	
BUS ROUTE NO.		
BUS ADVERT (Y/N)	N	

SECTION 1: PARTS & CONSUMABLE ITEMS (MATERIAL COST)

NO.	Part or Item Description Quantity		Total Cost	
1	SIDE LAMP INDICATOR	1	\$	176.00
		9% GST	\$	15.84
		PARTS TOTAL COST	\$	191.84

SECTION 2: ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)			TOTAL COST	
TO DISMANTLE & REPLACE :-				
DISMANTLE AND REPLACE ITEM NO 1		\$	650.00	
TO REMOVE & INSTALL PARTS SO AS TO PERFORM REPAIR WORKS :-				
OS REAR CORNER DOMEOS REAR CCTV CAMERA COVER		\$	1,300.00	
SPRAY PAINTING :-				
OS REAR CORNER DOMEOS REAR CCTV CAMERA COVER		\$	1,280.00	
SPRAY PAINTING \$640 PER PANEL		9% GST	\$	290.70
LABOUR CHARGES \$650 PER DAY		LABOUR TOTAL COST	\$	3,520.70

SECTION 3: NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

		DATE IN	17/Jun/2024
		DATE & TIME SURVE	Υ
		DATE OUT	
BUS TYPE (SD / DD)	DD	TOTAL NUMBER OF DAYS	4
LOSS OF USE COST		\$1,6	00.00

1				
SUMMARY				
SECTION NO.	COST			
1	\$	191.84		
2	\$	3,520.70		
3	\$	1,600.00		
TOTAL	\$	5,312.54		

PAGE 1