



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2502047

INV Date 04/04/2025

Reference CD/LPC24090229/Rua3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SBT 9988L
Insured Veh. YQ 6528U
Claim No. 24/24/24/VC05/029851
Policy No. Z24VC05023696-001
Accident Date 30/07/2024
Inspection Date 13/09/2024

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CD/LPC24090229/Rua3q2(N)	
			Date: 04/04/2025	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YQ 6528U	Veh. Inspected	SBT 9988L
	Policy No.	Z24VC05023696-001	Coverage (\$)	0.00
	Claim No.	24/24/24/VC05/029851	Excess (\$)	0.00
	Assign From	GERALD	Assign Date	13/09/2024
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ C 200 KOMP	c.c	1796
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	WDD2040412A235832	Colour	BLACK
	Odometer	131996 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	MICHELIN	6 mm
	L/H Front Tyre	225/45 R17	MICHELIN	6 mm
	R/H Rear Tyre	225/45 R17	MICHELIN	6 mm
	L/H Rear Tyre	225/45 R17	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	30/07/2024	Inspection Date	13/09/2024
	Survey held at	XINYA AUTO SERVICES PTE LTD BLK 1002 BUKIT MERAH LANE 3 #01-75 SINGAPORE 159719		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBT 9988L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	1,680.00	1,680.00
1	FRONT BUMPER RETAINER	SERVICEABLE	155.00	-
1	SET FRONT BUMPER SENSOR	SHORTED	585.00	585.00
15	FRONT BUMPER CLIPS	NECESSARY	150.00	150.00
1	FRONT BUMPER LOWER CHROME	CRACKED	185.00	185.00
1	FRONT BUMPER NOS PLATE HOLDER	CRACKED	195.00	195.00
1	FRONT BUMPER GRILLE	CRACKED	1,560.00	1,560.00
1	FRONT BUMPER FOG LAMP	SERVICEABLE	385.00	-
1	FRONT BUMPER FOG LAMP CHROME	SCRATCHED	295.00	295.00
1	FRONT BUMPER HEADLAMP	SERVICEABLE	2,860.00	-
	LESS 10% DISCOUNT		-805.00	-465.00
			7,245.00	4,185.00
	<u>LABOUR</u>			
	TO REMOVE & REPLACE FRONT BUMPER ,HEADLAMP ,AND PANEL BEAT & ALIGN CHASSIS PANEL.		1,200.00	550.00
	TO PUTTY & SPRAY PAINT FRONT BUMPER AND OTHER OTHER AFFECTED AREA.		600.00	250.00
	TO CHECK & RECTIFY HEADLAMP & FOCUS HEADLAMP.		80.00	30.00
			1,880.00	830.00
	GRAND TOTAL		9,125.00	5,015.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,000.00

Report Ref No. CD/LPC24090229/Rua3q2(N)

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SBT 9988L



PHOTOGRAPHS FOR VEHICLE NO. : SBT 9988L



PHOTOGRAPHS FOR VEHICLE NO. : SBT 9988L



PHOTOGRAPHS FOR VEHICLE NO. : SBT 9988L



PHOTOGRAPHS FOR VEHICLE NO. : SBT 9988L



PHOTOGRAPHS FOR VEHICLE NO. : SBT 9988L



PHOTOGRAPHS FOR VEHICLE NO. : SBT 9988L



PHOTOGRAPHS FOR VEHICLE NO. : SBT 9988L



PHOTOGRAPHS FOR VEHICLE NO. : SBT 9988L



PHOTOGRAPHS FOR VEHICLE NO. : SBT 9988L



PHOTOGRAPHS FOR VEHICLE NO. : SBT 9988L



PHOTOGRAPHS FOR VEHICLE NO. : SBT 9988L





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SBT 9988L



PHOTOGRAPHS FOR VEHICLE NO. : SBT 9988L





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SBT 9988L





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SBT 9988L

