

XINYA AUTO SERVICES PTE LTD

Address: BLK 1002 BUKIT MERAH LANE 3 #01-75 SINGAPORE 159719

E-mail : xinyaauto@gmail.com

Tel: 6270 3481 Fax: 6278 7522

Date : 13-Sep-24

Address : LIM BOEY TEE
BLK 114 BUKIT PURMEI ROAD
#08-255
SINGAPORE 090114

Reference : TP 1383/09/24
Vehicle No : SBT9988L
Make/Model : MERCEDES C200
Insurance Co. : INCOME

RE : QUOTATION TO SBT9988L FOR THIRD PARTY CLAIMS.

PARTS REQUIRED

		QTY	AMT \$
1)	FRONT BUMPER <i>de</i>	1	1,680.00
2)	FRONT BUMPER RETAINER <i>YSL</i>	1	155.00 X
3)	FRONT BUMPER SENSOR <i>short</i>	1 SET	585.00
4)	FRONT BUMPER CLIPS <i>re</i>	15	150.00
5)	FRONT BUMPER LOWER CHROME <i>con</i>	1	185.00
6)	FRONT BUMPER NOS PLATE HOLDER <i>con</i>	1	195.00
7)	FRONT BUMPER GRILLE <i>con</i>	1	1,560.00
8)	FRONT BUMPER FOG LAMP <i>? YSL</i>	1	385.00 X
9)	FRONT BUMPER FOG LAMP CHROME <i>con</i>	1	295.00
10)	FRONT BUMPER HEADLAMP <i>? YSL</i>	1	2,860.00 X

LIST PRICE TOTAL *4650* \$ 8,050.00
LESS DISCOUNT 10% *10%* \$ 805.00
LIST PRICE TOTAL AFTER LESS *4185* \$ 7,245.00

NETT PRICE TOTAL \$0.00

TOTAL PARTS COST **\$7,245.00**

LABOUR AND MISCELLANEOUS CHARGES

1)	TO REMOVE & REPLACE FRONT BUMPER, HEADLAMP, AND PANEL BEAT & ALIGN CHASSIS PANEL	\$ 1,200.00 (6 DAYS)
2)	TO PUTTY & SPRAY PAINT FRONT BUMPER AND OTHER OTHER AFFECTED AREA.	\$ 250.00 (2 PANELS)

400 + 150 = 550

3) TO CHECK & RECTIFY HEADLAMP & FOCUS HEADLAMP

\$ ~~80.00~~ 30

LABOUR TOTAL

\$ 1,880.00

TOTAL ESTIMATED REPAIR COST

\$ 9,125.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4185

830

5015

20%

4012

45-\$4,000/3 days Reg after repair

Raeu

Hp 90010068

3 days

L/S

13/09/24