

Not Authored
Penny B4 paint

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD314D

AAD2409-

01897.35

13 SEP 2024

Vehicle No.:
Chassis No.:
Co UEN:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

SHD314D

JTDKB3FU703097033

200303878K

TOYOTA

PRIUS GEN 4

11/9/2024

SHC2798H/MSFCI

28/9/2023

PART

LIST

- 1 COVER, REAR BUMPER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 REFLECTOR ASSY, REFLEX, LH
- 1 REFLECTOR ASSY, REFLEX, RH
- 1 COVER, FLOOR UNDER, NO.1 LH
- 1 COVER, FLOOR UNDER, NO.2 RH
- 1 COVER, REAR FLOOR CTR
- 1 COVER, DECK TRIM, REAR
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 PANEL SUB-ASSY, BACK DOOR

\$	Buclom	612.68	✓
\$	Bu	419.90	✓
\$	Sur	27.93	✓
\$	Bu	472.19	✓
\$	Sn	167.48	X
\$	Sn	167.48	X
\$	Sn	49.25	X
\$	Sn	49.25	✓
\$	Sn	220.50	X
\$	Sn	304.92	X
\$	CM Bu	290.43	✓
\$	Sn	159.39	X
\$	R	824.46	X
\$	R	1,443.86	X

TOTAL \$ 5,209.72

25% \$ 1,302.43

\$ 3,907.29

Special Nett

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL
- 1 REAR BUMPER PROTECTOR
- 2 SEAM SEALANT
- 1SET REAR BUMPER RETAINER CLIP

\$	Sn	700.00	X
\$	Me	95.00	6000
\$	na	150.00	X
\$	na	200.00	X
\$	na	130.00	X
\$	NP	180.00	X
\$	na	250.00	X
\$	na	85.00	X

Trans-cab Auto Services Pte Ltd**AAD2409-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD314D

1 END PANEL TRIM CLIP

\$ *nn* 65.00 *X***TOTAL \$ 1,855.00****TOTAL PARTS \$ 5,762.29****LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$ *nn* 300.00 *X*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 *X*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,600.00 *200*

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ 380.00 *X*

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ *nn* 180.00 *X*

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ *nn* 250.00 *X*

Putty And Spray Painting Of The Affected Portion.

\$ 1,600.00 *500 2200*

To reinstall rear bumper parking sensor.

\$ 170.00 *500*

To Check Electrical Lighting Concerned.

\$ *nn* 170.00 *X***TOTAL \$ 5,030.00****Over All Total \$ 10,792.29****(PART-BY-PART) Repair Days***8 DAYS*
*2 days***LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: