

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

ESTIMATE

12/9/2024

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-06 IOB BUILDING
SINGAPORE 049711.

Vehicle No: PD544L
Vehicle Model: T/HIACE
Est No: 24090137
Claims ref:
Accident Date: 21/08/24
In Charge: JUNIOR
Remarks:

No	Description	Qty	U. Price	Amounts S\$
LIST ITEMS:				
1	FRONT BUMPER <i>cut</i> ✓	1	PC \$ 1,300.00	\$ 1,300.00
2	HEADLAMP LH <i>X</i>	1	PC \$ 1,700.00	\$ 1,700.00
3	FRONT SIDE PANEL LH - REPAIR <i>X</i>	1	PC	\$ -
4	FRONT DOOR LH - REPAIR	1	PC	\$ -
5	FRONT STEP PANEL LH <i>X</i>	1	PC \$ 490.00	\$ 490.00
6	FRONT TYRE CAP LH <i>X</i>	1	PC \$ 170.00	\$ 170.00
7	SIDE MIRROR ASSY LH <i>Crack</i> ✓	1	PC \$ 680.00	\$ 680.00
LIST TOTAL S\$				\$ 4,340.00
25% DISCOUNT S\$				\$ (1,085.00)
				<u>\$ 3,255.00</u>

LABOUR CHARGE:

1	TO CUT, WELD, PANEL BEAT, STRAIGHTEN, REPLACE DAMAGED PARTS & REALIGN AFFECTED AREAS	\$ 500.00 <i>300</i>
2	TO PUTTY SPRAY PAINT ON FRONT DOOR LH, FRONT SIDE PANEL LH	\$ 450.00 <i>250</i>
3	TO RESET & REPROGRAMMING AFTER ACCIDENT REPAIR WORKS	\$ 150.00 <i>X</i>
4	TO CHECK STEERING GEOMETRY & CONDUCT WHEEL ALIGNMENT	\$ 80.00 <i>X</i>
TOTAL LABOUR COST S\$		<u>\$ 1,180.00</u>

AMOUNT S\$ \$ 4,435.00
GST @ 9% \$ 399.15

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

ESTIMATE

12/9/2024

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-06 IOB BUILDING
SINGAPORE 049711.

Vehicle No: PD544L
Vehicle Model: T/HIACE
Est No: 24090137
Claims ref:
Accident Date: 21/08/24
In Charge: JUNIOR
Remarks:

No	Description	Qty	U. Price	Amounts S\$
			AMOUNT DUE S\$	\$ 4,834.15
Customer's Signature		MOVA AUTOMOTIVE PTE LTD		

Plsme
Ap 9wmb8
3clap
p/p
17/09/24
Reg after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: