

(08/11/13) wef
ASS. REC. BY:

REF: CS/MSH24096233/RVP3

7240

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKZ15506

at Workshop m/s CYCLE & CARRIAGE
of PANDAN LOUP

Insured:

MS/4

Policy No. 1002966659

Claims No. 373082

Sum Insured:

Excess:


TBA 0

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

48K

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKZ15506

Yr Regn:

2016 Jan

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: MERCEDES BENZ C200 AVANTAR C.C. 1991

Colour

WHITE

AC: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD 2050422R12169

Gen. Cond: Good / Fair / Poor / ☒ Burnt

Steering: Inorder / Jammed / Leaked / ☒ Burnt or

Brake: Inorder / Jammed / Leaked / ☒ Burnt or

Modi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size:

F:

225/50R17

R:

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

11/09/24

D.O.I.

13/09/24

Survey held at

PANDAN LOUP

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 15K

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: 18

Resurvey No. of Trip:

Investigation- \$550 SCDF-\$170

Survey Fee:

Transportation:

: S + RS \$

: Photos

: Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Z BP-GRA
TP VE
TOW
DAT
NC
B
B
L
B
F



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKZ1550E

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807
68277888

Vehicle & Document Information
WIP No 20788
Reg No/Reg Date SKZ1550E / 04/01/2016
Date In/Mileage / 0
Chassis No WDD2050422R122169
Engine No 27492030478461
Make/Model MB/MB C 200 SEDAN (W205) "AVANTGARDE / A
Colour/Trim 027 799 Diamond Whi/ 042 201 Black

Account No	Terms	Date/Time Printed	CSE	Operator
WI000558	Credit	13/09/2024/ 16:05	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

Z REQUEST

Customer Request
M BPNSUN
POLICY NO/ACC DATE : B300915912QMY // 11-9-2024
TOW IN/EXCESS : 11-9-2024 // TBA
DATE IN/DATE SURVEY:
BY/AUTHORIZED ON :

A BPILAB

TO REMOVE & INSTALL AFFECTED BODY PANEL FOR REPAIRS

A BPIRES

RESPRAY ENGINE HOOD

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT

A BPILAB

EXTRACT REFRIGERANT, CHECK FOR LEAKS, REFILL (WHEN WORKING ON AIR CONDITIONING)

A BPILAB

FRAME FLOOR WIRING HARNESS REPLACE WITH REMOVE/INSTALL EVAPORATOR UNIT INSTRUMENT PANEL & HEADLINE & STEERING COLUMN & AIRBAG & FUSE BOX DETACHABLE PARTS IN AREA TO BE REPAIRED.

A BPILAB

TO WASH FIRE EXTINGUISHER POWDER.

A BPILAB

TO DROP AND REFIT / RENEW 'ABR' PUMP AND CONTROL UNIT, TO BLEED AND RESET 'ESP' SYSTEM.

A 97250001

CAVITY PRESERVATION ON REPLACED OR REPAIRED BODY PANELS PERFORM

M BATTERY SENSOR

M INSULATING CAP

M INSULATING CAP

M CURRENT LIMITER

M EQUIPMENT COMPARTMENT

1.00	448.90	00.00	448.90
1.00	9.33	00.00	9.33
1.00	9.33	00.00	9.33
1.00	441.74	00.00	441.74
1.00	120.75	00.00	120.75

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKZ1550E

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807
68277888

Vehicle & Document Information

WIP No 20788
Reg No/Reg Date SKZ1550E / 04/01/2016
Date In/Mileage / 0
Chassis No WDD2050422R122169
Engine No 27492030478461
Make/Model MB/MB C 200 SEDAN (W205) "AVANTGARDE" / A
Colour/Trim 027 799 Diamond Whi/ 042 201 Black

Account No	Terms	Date/Time Printed	CSE	Operator
WI000558	Credit	13/09/2024/ 16:05	CH	371 / Go Chee Han

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M RH/FRONT RELAY UNIT	1.00	591.71	00.00	591.71
M FUSE CARRIER	1.00	6.31	00.00	6.31
M COVER, EQP. COMPARTMENT	1.00	49.13	00.00	49.13
M INFO SHT. RELAYS + FUSES	1.00	8.61	00.00	8.61
M ENGINE ELECTRICAL WIRING HARNESS	1.00	2611.73	00.00	2611.73
M FUSE BOX ELECTRICAL WIRING HARNESS	1.00	168.72	00.00	168.72
M MAIN ELECTRICAL WIRING HARNESS	1.00	5749.95	00.00	5749.95
M RIGHT WHEEL HOUSE PARTITION	1.00	137.87	00.00	137.87
M CTR/FIREWALL PARTITION	1.00	190.74	00.00	190.74
M DAMPENING, FIREWALL	1.00	196.05	00.00	196.05
M RIGHT WATER BAFFLE	1.00	263.40	00.00	263.40
M RIGHT SIDE SEAL, AIR DUCT	1.00	14.89	00.00	14.89
M SEALING, AIR DUCT	1.00	56.04	00.00	56.04
M EXPANSION RIVET	2.00	3.33	00.00	6.66
M FEED-THROUGH GROMMET	1.00	2.92	00.00	2.92
M RIGHT DRAIN VALVE	1.00	58.65	00.00	58.65
M LEFT WATER BAFFLE	1.00	314.54	00.00	314.54

Rasul
Hp 9001068

18 clump

13/09/24

EXCESS: TRA

Revert

Rey after repair
P/P

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirmed & accepted by

Nett 34,597.97
9% GST on 34597.97 3113.82

Total Payable 37,711.79

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	724C
Vehicle Details	
Vehicle No.:	SKZ1550E
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Sep 2024
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C200 AVANTGARDE (R17 LED)
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	27492030478461
Chassis No.:	WDD2050422R122169
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$40,985.00
Original Registration Date:	04 Jan 2016
First Registration Date:	04 Jan 2016
Transfer Count:	1
Actual ARF Paid:	\$44,379.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Jan 2026
PARF Rebate Amount:	\$24,408.00
Intended COE Rebate Details	
COE Expiry Date:	03 Jan 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$60,001.00
COE Rebate Amount:	\$7,806.00
Total Rebate Amount:	\$32,214.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 15 Sep 2024

OK



Mercedes-Benz C-Class C200 Avantgarde

\$48,800 Instalment \$2,511/mth

💰 Apply for 2.48% loan

♡ Shortlist

✔ Get Warranty

NEW CAR DISCOUNTS & OFFERS

BEST DEAL DAILY!

▶ **VIEW ALL
PROMO**

Overview Financial Photo Research

Depreciation	ⓘ \$20,860 / year
Reg. Date	07-Jan-2016 (1yr 3mths 22days COE left)
Manufactured	ⓘ 2015
Mileage	110,000 km (12.6k / year)
Transmission	Auto
Engine Cap	1,991 cc
Road Tax	ⓘ \$1,202 / year
Power	135.0 kW (181 bhp) View specs of the Mercedes-Benz C-Class Saloon (2014-2018)
Curb Weight	ⓘ 1,465 kg
COE	ⓘ \$61,103
OMV	ⓘ \$39,977
ARF	ⓘ \$42,968