

WE GARAGE

11 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit, Singapore 417883

wegarage@consultant.com

Mobile : +65 9009 6622

LKK Auto Consultants Singapore
 the Repairer of the following:
 • To re-spray before/after spray painting
 • To display damaged parts, and re-spray
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be re-surveyed and
 • All repairs must be approved by the relevant Insurance Company
 Acknowledged by Repairer

Not Authorized

13 September 2024

REG NO. : SJD144D
 MAKE/MODEL : INFINITY Q50 3.0T SPORT

*13/9/24
 4/5 @ 3900 /
 # days
 Take photo After rep-*

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
NETT ITEMS		
1	Rear Tail Gate	\$ R 1,558.90 X
2	Rear Tail Lamp - RHS & LHS @ 878.50	\$ 0/scr0 17,576.00 PC
1	Rear Tailgate "LOGO" Emblem	\$ Scr 78.50 X
1	Rear Tailgate "Q50S" Emblem	\$ Scr 58.80 X
1	Rear Tailgate Upper Moulding	\$ 11 1,104.60 X
1	Rear Tailgate Lower Moulding	\$ 11 1,208.40 X
2	Lamp RH & LH @ 472	\$ 11 944.00 X
1	Rear Tailgate Lock	\$ 11 380.60 X
1	Rear End Panel	\$ R 918.00 X
1	Rear End Panel Inner Garnish	\$ 11 325.00 X
1	Rear Bumper	\$ 20/10,11 1,339.30 ✓
2	Rear Bumper Side Brackets @ 48	\$ 11 96.00 X
2	Rear Bumper Reflectors @ 84	\$ 0/scr0 168.00 PC
1	Rear Bumper Reinforcement	\$ 80 3erf 1,104.60 ✓
2	Rear Bumper Reinforcement Bracket @ 298.8	\$ 242.50 0/scr0 597.60 PC
2	Rear Bumper Side Retainers @ 69	\$ 11 138.00 X
4	Rear Bumper PDC Sensors @ 224.8	\$ Scr 899.20 X
1	Rear Bumper Tow Hook Cover	\$ 45.00 Torn 80.80 ✓
1	Rear Number Plate Lamps	\$ 11 180.00 X
		\$ 28,756.30
	Less 10%	\$ 2,875.63
		\$ 25,880.67
SPECIAL NETT ITEMS		
1	Wrapping Sticker	\$ nec 1,200.00 400
1	Rear Tailgate Spoiler	\$ 11 1,568.80 X
1	Rear Bumper Clip (1 Set)	\$ 11 120.00 40
		\$ 2,888.80
LABOUR CHARGES		
1	To Remove, Replaced Damaged Lamps And Check Up Rear Wiring.	\$ 80.00 20
2	To Remove And Refit Inner Garnishes	\$ 180.00 50
3	To Remove And Refit Rear Reverse Sensor	\$ 180.00 30
4	To Transfer Rear Tailgate Mechanism And Wiring Assembly	\$ 11 80.00 X
5	To Apply Undercoating.	\$ 11 200.00 X
6	Panel Beating.	\$ 1,800.00 550
7	To Re-spray Painting On The Affected Areas.	\$ 1,600.00 600
		\$ 4,120.00
GRAND TOTAL :		\$ 32,889.47

*p-3569.30
 102
 3212.37
 440
 1250*