

LH Express Motor Trading

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/P 91082728

NOT Withheld
L1 Lp & 5050p
Resurvey After Paint
6 days

Chew Kok Leong
Blk 186D Rivervale Drive
#07-842
Singapore 544186

Vehicle No : SNH 4730 S
Make/Model : Toyota Estima Aeras
Year : 2007

| Qty | Description | Unit Price | Amount |
|--------------------------------|---|----------------------|------------------|
| Estimate Cost Of Repair | | | |
| 1 pc | Rear tail-gate assy <i>1619</i> | Ry \$1,955.70 | ✓ |
| 1 pc | Rear tail-gate glass moulding | Me \$95.60 | ✓ |
| 1 pc | Rear tail-gate outer chrome handle | Sm \$265.10 | X |
| 1 pc | Rear tail-gate emblem " Logo " | Me \$65.70 | ✓ |
| 1 pc | Rear tail-gate emblem " Estima " | Me \$68.70 | ✓ |
| 1 pc | Rear tail-gate emblem " Aeras " | Me \$60.10 | ✓ |
| 1 pc | Rear tail-gate inner lock | De \$481.70 | ✓ |
| 1 pc | Rear tail-gate inner trim board | Sm \$552.70 | X |
| 1 pc | Rear boot rubber | De \$346.10 | -50 bin 173.055w |
| 1 pc | Rear end panel <i>photo</i> | Ry \$655.80 | ✓ |
| 1 pc | Rear end panel top garnish <i>photo</i> | My car \$266.20 | ✓ |
| 1 pc | Rear end panel lower garnish <i>photo</i> | Bu \$225.10 | ✓ |
| 1 pc | Rear bumper - colour code <i>photo</i> | Bu \$1,055.20 | ✓ |
| 1 pc | Rear bumper side retainer | \$75.10 Sm \$150.20 | X |
| 2 pcs | Rear bumper sponge | \$115.10 Sm \$230.20 | X |
| 2 pcs | Radio antenna <i>photo</i> | De \$185.70 | ✓ |
| 1 pc | Rear boot floor panel <i>photo</i> | R \$955.60 | X |
| 1 pc | Rear fender inner trim board | My car \$755.10 | ✓ |
| | | | \$1,510.20 ✓ |
| | | | \$9,125.60 |
| | | Less 25 % | \$2,281.40 |
| | | | \$6,844.20 |

S Nett

1 pc Rear tail-gate glass sealant
1 set Rear reverse sensor
20 pcs Rear bumper clip
1 pc Rear no plate

Me \$40.00 ✓
De \$200.00 ✓
\$2.00 Me \$40.00 ✓
Sm \$40.00 X
\$320.00

balance c/f \$7,164.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SNH 4730 S

balance b/f \$7,164.20

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$1,500.00 *800*

To putty and spray paint

\$1,500.00 *800*

Check & reconnect wiring.

\$40.00 *200*

To apply underseal and anti-rust proofing on affected areas

\$120.00 *600*

Remove/refit rear windscreen to facilitate repair

\$120.00 ✓

Remove/refit rear tail-gate mechanism to new door.

\$100.00 *800*

Total

\$10,544.20