

Not Authorized
1 Ring &

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5865C

AAD2406-015

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC5865C

JTDKB3FU603093863

200303878K

TOYOTA

PRIUS GEN 4

3/6/2024

GZ629X/ *Chinese*

26/2/2021

PART

- 1 COVER, FRONT BUMPER
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 SUPPORT, FRONT BUMPER SIDE, RH
- 1 MOULDING, FRONT BUMPER SIDE, RH
- 1 JAR ASSY, WINDSHIELD WASHER
- 1 UNIT ASSY, HEADLAMP, RH
- 1 FENDER SUB-ASSY, FRONT RH
- 1 LINER, FRONT FENDER, RH
- 1 EMBLEM, SIDE PANEL, RH
- 1 UNIT ASSY, HEADLAMP, RH

LIST	
\$ <i>Bu/Am</i>	653.31 ✓
\$ <i>Am</i>	100.91 X
\$ <i>Am</i>	902.16 X
\$ <i>Am</i>	100.49 X
\$ <i>Am</i>	120.86 X
\$ <i>Am</i>	276.15 X
\$ <i>Am</i>	3,325.56 X
\$ <i>Am</i>	1,236.69 ✓
\$ <i>DIT</i>	255.36 ✓
\$ <i>Am</i>	68.88 ✓
\$ <i>Am</i>	3,325.56 X
TOTAL \$	10,365.93
25% \$	2,591.48
\$	7,774.44

Special Nett

- 1 FRT BUMPER CLIP
- 1 FENDER LINER CLIP
- 1 FRT BUMPER SIDE RETAINER CLIP

\$ <i>Am</i>	65.00 <i>60Am</i>
\$ <i>Am</i>	65.00 <i>60Am</i>
\$ <i>Am</i>	65.00 X
TOTAL \$	195.00

TOTAL PARTS \$ 7,969.44

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$

250.00 *301*

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2406-015

SHC5865C

Putty And Spray Painting Of The Affected Portion.	\$	1,800.00	4001
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	15/
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,000.00	400
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of rear fender panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
TOTAL	\$	4,990.00	
Over All Total	\$	12,959.44	

(PART-BY-PART) Repair Days**04 Days****2 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: