

WE GARAGE

11 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit, Singapore 417883

wegarage@consultant.com

Mobile : +65 9009 6622

Not Authorized

17/9/24

17 September 2024

REG NO. : SNL8688J

MAKE/MODEL : HONDA VEZEL HYBRID e:HEV X

2/5 @ 2800
3 days

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Front LH Headlamp	2,648.20 ✓
1	Front Bumper	1,228.80 ✓
1	Front Bumper Inner Sponge	241.10 X
1	Front Bumper Reinforcement	786.90 X
1	Front Bumper Lower Lid	678.80 X
1	Front Bumper Side Retainer	128.00 X
1	Front Bumper PDC Sensor	268.20 X
1	Front LH Fender	598.00 X
1	Front LH Fender Inner Shield	387.40 X
1	Front LH Fender Wheel Arch Garnish	389.50 ✓
1	Front LH Wheel Rim	1,280.00 X
1	Front Wheel Hub With Bearing	587.54 X
1	Front Shock Absorber	527.78 X
1	Front Knuckle Arm	627.09 X
1	Front Lower Arm	638.00 X
		\$ 11,015.31
	Less 20%	\$ 2,203.06
		\$ 8,812.25
<u>SPECIAL NETT ITEMS</u>		
1	Front Tyre	450.00 X
1	Front Fender Inner Shield Clip (1 Set)	80.00 X
1	Front Bumper Clip (1 Set)	90.00 305/11
		\$ 620.00
<u>LABOUR CHARGES</u>		
1	To Check Wiring, Lighting And Resetting Headlamps Focusing	80.00 20
2	To Remove And Refit Front Sensor.	180.00 30
3	To Remove And Refit Front Undercarriage.	350.00 X
4	To Conduct Wheel Alignment	180.00 X
5	To Apply Undercoating.	180.00 X
6	Panel Beating.	1,500.00 300
7	To Re-spray Painting On The Affected Areas.	1,400.00 400
		\$ 3,870.00

\$ 13,302.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey GRAND TOTAL
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page 1 of 1

Acknowledged by Repairer

Signature:

Date:

P-3411-1

202

2728.88

30

750

3508.88

2007