

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Xiao Chun

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0686/2024/KS
17-Sep-24
GLORY
1 of 1
SMX 9150 K
AUDI A3 SEDAN 1.0 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND COANTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00	✓
2	TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.	\$ 1,250.00	✓
3	TO REPAIR LHS FRONT FENDER TOP SUPPORT.	\$ 250.00	✓
4	TO RESPRAY LHS FRONT FENDER TOP SUPPORT.	\$ 250.00	✓
Parts			
1	FRONT LOCK CARRIER <i>could</i>	\$ 908.00	✓
2	MIX COOLANT 1.0 LITER <i>m</i>	6 \$ 332.00	✓
3	HEADLIGHT LED HEAT SINK LHS <i>could</i>	\$ 924.00	✓
4	AIRCON STICKER <i>3 new</i>	\$ 10.00	✓
5	CAUTION STICKER	\$ 25.00	✓
GRAND TOTAL		\$ 5,349.00	

For Premium Automobiles Pte Ltd

Adrian L
Slis

Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 9150 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS AND OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER.	S/N \$ 360.00 ✓	
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 250	
3	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND INSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR.	S/N \$ 280.00 ✓	
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHTS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,800.00 1500	
5	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, LHS FRONT DOOR AND LHS A-PILLAR.	\$ 4,000.00 2100 2750	HL
6	TO RENEW LHS FRONT RIM AND CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 560.00 500 280	HL
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 292.00 ✓	S.
8	TO RE-APPLY PAINT PROTECTION FILM ON ACCIDENT AFFECTED PANELS.	S/N -	
TOTAL LABOUR CHARGES		: \$ <u>8,642.00</u>	

+ 5 days additional days

(3 days - Lock carrier.
 1 day - fender bp support
 1 day - Lhs A-pillar)

add 4 days
 H.S.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



Accident - 7 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 9150 K.

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Distorted</i>	1	\$ 2,736.00	✓	
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 209.00	✓	
3	FRONT BUMPER GUIDE SECTION - LH <i>Crushed</i>	1	\$ 49.00	✓	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Crushed</i>	1	\$ 645.00	✓	
5	FRONT BUMPER CLOSING ELEMENT - LH <i>Crushed</i>	1	\$ 357.00	✓	
6	FRONT BUMPER TRIM - LH <i>Crushed</i>	1	\$ 204.00	✓	
7	FRONT BUMPER ADAPTOR - LH <i>new</i>	1	\$ 48.00	✓	
8	RADIATOR GRILLE <i>Crushed</i>	1	\$ 1,784.00	✓	<i>sls</i>
9	FRONT BUMPER CLOSING ELEMENT <i>new</i>	1	\$ 235.00	+	
10	FRONT BUMPER AIR GUIDE GRILLE - LH <i>Missing</i>	1	\$ 236.00	✓	
11	FRONT REINFORCEMENT BEAM COVER ?	1	\$ 153.00	?	
12	FRONT FOAM FILLER PIECE <i>Crushed</i>	1	\$ 237.00	✓	
13	FRONT REINFORCEMENT BEAM ?	1	\$ 1,055.00	?	
14	OUTSIDE TEMP SENSOR BRACKET ?	1	\$ 30.00	?	
15	LED HEADLIGHT - LH <i>Crushed</i>	1	\$ 6,647.00	✓	
16	LED HEADLIGHT POWER MODULE - LH <i>from</i>	1	\$ 904.00	+	
17	LED HEADLIGHT CONTROL UNIT - LH	1	\$ 664.00	+	
18	LIFT CYLINDER - LH <i>new</i>	1	\$ 170.00	✓	<i>sls</i>
19	LIFT CYLINDER HOSE <i>new</i>	1	\$ 86.00	✓	
20	FRONT FENDER - LH <i>Distorted</i>	1	\$ 1,016.00	✓	
SUB TOTAL SPARE PARTS			\$ 17,465.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 9150 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER ATTACHMENT PARTS - LH ?	1	\$ 85.00	?
22	FRONT FENDER BRACKET - LH ?	1	\$ 45.00	✓
23	FRONT FENDER BRACKET - LH Best	1	\$ 72.00	✓
24	FRONT FENDER RIVET m	5	\$ 21.00	✓
25	FRONT FENDER BRACE Best	1	\$ 122.00	✓
26	FRONT WHEEL HOUSING LINER SEAL - LH ?	1	\$ 43.00	?
27	FRONT WHEEL HOUSING LINER - LH Deland	1	\$ 204.00	✓
28	FRONT WHEEL HOUSING LINER ATTACHMENT PART m	1	\$ 105.00	+
29	BONNET Deland	1	\$ 3,392.00	✓
30	BONNET ATTACHMENT PARTS neu	1	\$ 184.00	+
31	BONNET HINGE - LH / RH neu	2	\$ 150.00	+
32	BONNET CATCH HOOK neu	1	\$ 116.00	+
33	BONNET STRIKER - LH / RH neu	2	\$ 274.00	+
34	BONNET EDGE PROTECTION neu	1	\$ 35.00	✓
35	BONNET LOCK WITH MICROSWITCH neu	2	\$ 491.00	+
36	WASH WATER RESERVOIR Deland	1	\$ 238.00	✓
37	WASH WATER RESERVOIR STRAINER neu	1	\$ 26.00	+
38	WASH WATER RESERVOIR END CAP neu	1	\$ 26.00	+
39	WINDSCREEN WASHER PUMP neu	1	\$ 147.00	+
40	HORN At Dwyd	1	\$ 239.00	✓ H.S.
SUB TOTAL SPARE PARTS		:	\$ 6,015.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.