

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0686/2024/KS
DATE : 13-Sep-24
WIP : 30813

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 16/9/2024.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Hi Adrian,

10 Days + 1 Sun - OK - Allan Boo

14-Oct-24

OWNER'S NAME : MR. ONG THIAM HOCK
ADDRESS : 29 SIMEI ST 3
#09-11
SINGAPORE 529901
TELEPHONE : HP +65 93369429
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210013751-01
VEHICLE NO : **SMX 9150 K**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI
MODEL YEAR : 4/2/2021
ENGINE NO : CHZ C34819
CHASSIS NO : WAUZZZ8V3LA032941
MILEAGE : KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 12-Sep-24
PLACE OF ACCIDENT : JURONG WEST CENTRAL 1

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 9150 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS	
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS AND OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER.	S/N \$	360.00	\$	360.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	\$	250.00
3	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND INSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR.	S/N \$	280.00	\$	280.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHTS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,800.00	\$	1,500.00
5	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, LHS FRONT DOOR AND LHS A-PILLAR.	\$	4,000.00	\$	2,750.00
6	TO RENEW LHS FRONT RIM AND CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$	560.00	\$	560.00
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	\$	292.00
8	TO RE-APPLY PAINT PROTECTION FILM ON ACCIDENT AFFECTED PANELS.	S/N	-		
ADD LABOUR - SUPPLEMENTARY				\$	3,150.00
TOTAL LABOUR CHARGES		:	\$	8,642.00	\$ 9,142.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 9150 K.

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,736.00	\$	2,188.80
2	FRONT BUMPER FIXING PARTS	1	\$ 209.00		
3	FRONT BUMPER GUIDE SECTION - LH	1	\$ 49.00	\$	38.56
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 645.00	\$	515.60
5	FRONT BUMPER CLOSING ELEMENT - LH	1	\$ 357.00	\$	285.60
6	FRONT BUMPER TRIM - LH	1	\$ 204.00	\$	163.20
7	FRONT BUMPER ADAPTOR - LH	1	\$ 48.00		
8	RADIATOR GRILLE	1	\$ 1,784.00	\$	1,427.20
9	FRONT BUMPER CLOSING ELEMENT	1	\$ 235.00		
10	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 236.00	\$	188.40
11	FRONT REINFORCEMENT BEAM COVER	1	\$ 153.00		
12	FRONT FOAM FILLER PIECE	1	\$ 237.00	\$	189.60
13	FRONT REINFORCEMENT BEAM	1	\$ 1,055.00		
14	OUTSIDE TEMP SENSOR BRACKET	1	\$ 30.00		
15	LED HEADLIGHT - LH	1	\$ 6,647.00	\$	5,317.60
16	LED HEADLIGHT POWER MODULE - LH	1	\$ 904.00		
17	LED HEADLIGHT CONTROL UNIT - LH	1	\$ 664.00		
18	LIFT CYLINDER - LH	1	\$ 170.00	\$	136.00
19	LIFT CYLINDER HOSE	1	\$ 86.00	\$	68.56
20	FRONT FENDER - LH	1	\$ 1,016.00	\$	812.80
SUB TOTAL SPARE PARTS		:	\$ 17,465.00	\$	11,331.92

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 9150 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 11,331.92
21	FRONT FENDER ATTACHMENT PARTS - LH	1	\$ 85.00	
22	FRONT FENDER BRACKET - LH	1	\$ 45.00	\$ 35.28
23	FRONT FENDER BRACKET - LH	1	\$ 72.00	\$ 57.28
24	FRONT FENDER RIVET	5	\$ 21.00	\$ 16.80
25	FRONT FENDER BRACE	1	\$ 122.00	\$ 97.20
26	FRONT WHEEL HOUSING LINER SEAL - LH	1	\$ 43.00	
27	FRONT WHEEL HOUSING LINER - LH	1	\$ 204.00	\$ 162.80
28	FRONT WHEEL HOUSING LINER ATTACHMENT PART	1	\$ 105.00	
29	BONNET	1	\$ 3,392.00	\$ 2,713.60
30	BONNET ATTACHMENT PARTS	1	\$ 184.00	
31	BONNET HINGE - LH / RH	2	\$ 150.00	
32	BONNET CATCH HOOK	1	\$ 116.00	
33	BONNET STRIKER - LH / RH	2	\$ 274.00	
34	BONNET EDGE PROTECTION	1	\$ 35.00	
35	BONNET LOCK WITH MICROSWITCH	2	\$ 491.00	
36	WASH WATER RESERVOIR	1	\$ 238.00	\$ 190.00
37	WASH WATER RESERVOIR STRAINER	1	\$ 26.00	
38	WASH WATER RESERVOIR END CAP	1	\$ 26.00	
39	WINDSCREEN WASHER PUMP	1	\$ 147.00	
40	HORN	1	\$ 239.00	\$ 190.80
SUB TOTAL SPARE PARTS		:	\$ 6,015.00	\$ 14,795.68

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 9150 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 14,795.68
41	ALUMINIUM RIM - LH	1	\$ 1,464.00	\$ 1,171.20
42	ALUMINIUM RIM RUBBER VALVE - LH	1	\$ 5.00	
43	FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00
	ADD PARTS - SUPPLEMENTARY			\$ 1,757.20
44	SUNDRIES		\$ 600.00	\$ 17.36
TOTAL SPARE PARTS			\$ 25,609.00	\$ 17,801.44
TOTAL LABOUR CHARGES			\$ 8,642.00	\$ 9,142.00
GRAND TOTAL			\$ 34,251.00	\$ 26,943.44

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0686/2024/KS 17-Sep-24 GLORY 1 of 1 SMX 9150 K AUDI A3 SEDAN 1.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND COANTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00	\$ 1,400.00
2	TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.	\$ 1,250.00	\$ 1,250.00
3	TO REPAIR LHS FRONT FENDER TOP SUPPORT.	\$ 250.00	\$ 250.00
4	TO RESPRAY LHS FRONT FENDER TOP SUPPORT.	\$ 250.00	\$ 250.00
<u>Parts</u>			
1	FRONT LOCK CARRIER	\$ 908.00	\$ 726.00
2	MIX COOLANT 1.0 LITER	6 \$ 332.00	\$ 265.44
3	HEADLIGHT LED HEAT SINK LHS	\$ 924.00	\$ 738.80
4	AIRCON STICKER	\$ 10.00	\$ 7.52
5	CAUTION STICKER	\$ 25.00	\$ 19.44
PART		\$ 2,199.00	\$ 1,757.20
LABOUR		\$ 3,150.00	\$ 3,150.00
GRAND TOTAL		\$ 5,349.00	\$ 4,907.20

For Premium Automobiles Pte Ltd

Authorised Signature



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT