



Xiao Chun

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0686/2024/KS
17-Sep-24
GLORY
1 of 1
SMX 9150 K
AUDI A3 SEDAN 1.0 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND COANTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00	✓
2	TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.	\$ 1,250.00	✓
3	TO REPAIR LHS FRONT FENDER TOP SUPPORT.	\$ 250.00	✓
4	TO RESPRAY LHS FRONT FENDER TOP SUPPORT.	\$ 250.00	✓
Parts			
1	FRONT LOCK CARRIER <i>could</i>	\$ 908.00	✓ 726
2	MIX COOLANT 1.0 LITER <i>m</i>	6 \$ 332.00	✓ 265.44
3	HEADLIGHT LED HEAT SINK LHS <i>could</i>	\$ 924.00	✓ 738.80
4	AIRCON STICKER <i>3 new</i>	\$ 10.00	✓ 7.52
5	CAUTION STICKER	\$ 25.00	✓ 19.44
GRAND TOTAL		\$ 5,349.00	

For Premium Automobiles Pte Ltd

Admin LG
S.S.

Authorised Signature

Add 4 Days for supplementary items and recovery items.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 9150 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS AND OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER.	S/N \$ 360.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	250 ✓
3	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND INSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR.	S/N \$ 280.00	✓
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHTS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,800.00	1500 ✓
5	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, LHS FRONT DOOR AND LHS A-PILLAR.	\$ 4,000.00	2100 <u>2750</u> ✓
6	TO RENEW LHS FRONT RIM AND CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 560.00	7 500 280 ✓
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 292.00	✓
8	TO RE-APPLY PAINT PROTECTION FILM ON ACCIDENT AFFECTED PANELS.	S/N -	
TOTAL LABOUR CHARGES		\$ 8,642.00	

+ 5 days additional days
 3 days - Lock carrier.
 1 day - Fender to support
 1 day - Lhs A-pillar
 add 4 days
 H.S.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408689
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 9150 K.

Accident
- 7 days

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER Distorted	1	\$ 2,736.00	✓ 2188.80	
2	FRONT BUMPER FIXING PARTS New	1	\$ 209.00	+	
3	FRONT BUMPER GUIDE SECTION - LH Included	1	\$ 49.00	✓ 38.56	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE Delid	1	\$ 645.00	✓ 515.60	
5	FRONT BUMPER CLOSING ELEMENT - LH Delid	1	\$ 357.00	✓ 285.60	
6	FRONT BUMPER TRIM - LH Delid	1	\$ 204.00	✓ 163.20	
7	FRONT BUMPER ADAPTOR - LH New	1	\$ 48.00	+	
8	RADIATOR GRILLE Included	1	\$ 1,784.00	✓ 1477.20	HLs
9	FRONT BUMPER CLOSING ELEMENT New	1	\$ 235.00	+	
10	FRONT BUMPER AIR GUIDE GRILLE - LH Missing	1	\$ 236.00	✓ 188.40	
11	FRONT REINFORCEMENT BEAM COVER ? New	1	\$ 153.00	? X	
12	FRONT FOAM FILLER PIECE Included	1	\$ 237.00	✓ 189.60	
13	FRONT REINFORCEMENT BEAM ? New	1	\$ 1,055.00	? X	
14	OUTSIDE TEMP SENSOR BRACKET ? New	1	\$ 30.00	? X	
15	LED HEADLIGHT - LH Included	1	\$ 6,647.00	✓ 5317.60	
16	LED HEADLIGHT POWER MODULE - LH New	1	\$ 904.00	+	
17	LED HEADLIGHT CONTROL UNIT - LH New	1	\$ 664.00	+	
18	LIFT CYLINDER - LH Delid	1	\$ 170.00	✓ 136	HLs
19	LIFT CYLINDER HOSE New int	1	\$ 86.00	✓ 68.56	
20	FRONT FENDER - LH Distorted	1	\$ 1,016.00	✓ 812.80	
SUB TOTAL SPARE PARTS			\$	17,465.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 9150 K

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
21	FRONT FENDER ATTACHMENT PARTS - LH ? <i>nn</i>	1	\$ 85.00	? <i>X</i>		
22	FRONT FENDER BRACKET - LH <i>Best</i>	1	\$ 45.00	✓ <i>35.78</i>		
23	FRONT FENDER BRACKET - LH <i>Best</i>	1	\$ 72.00	✓ <i>57.78</i>		
24	FRONT FENDER RIVET <i>nn</i>	5	\$ 21.00	✓ <i>16.80</i>		
25	FRONT FENDER BRACE <i>Best</i>	1	\$ 122.00	✓ <i>97.20</i>		
26	FRONT WHEEL HOUSING LINER SEAL - LH ? <i>nn</i>	1	\$ 43.00	? <i>X</i>		
27	FRONT WHEEL HOUSING LINER - LH <i>Delud</i>	1	\$ 204.00	✓ <i>162.80</i>		
28	FRONT WHEEL HOUSING LINER ATTACHMENT PART <i>nn</i>	1	\$ 105.00	+		
29	BONNET <i>Delud</i>	1	\$ 3,392.00	✓ <i>2713.60</i>		
30	BONNET ATTACHMENT PARTS <i>nn</i>	1	\$ 184.00	+		
31	BONNET HINGE - LH / RH <i>nn</i>	2	\$ 150.00	+		
32	BONNET CATCH HOOK <i>nn</i>	1	\$ 116.00	+		
33	BONNET STRIKER - LH / RH <i>nn</i>	2	\$ 274.00	+		
34	BONNET EDGE PROTECTION <i>nn</i>	1	\$ 35.00	<i>X NN</i>		
35	BONNET LOCK WITH MICROSWITCH <i>nn</i>	2	\$ 491.00	+		
36	WASH WATER RESERVOIR <i>Delud</i>	1	\$ 238.00	✓ <i>190</i>		
37	WASH WATER RESERVOIR STRAINER <i>nn</i>	1	\$ 26.00	+		
38	WASH WATER RESERVOIR END CAP <i>nn</i>	1	\$ 26.00	+		
39	WINDSCREEN WASHER PUMP <i>nn</i>	1	\$ 147.00	+		
40	HORN <i>nn</i>	1	\$ 190.80	✓ <i>190.80</i>		
SUB TOTAL SPARE PARTS			\$ 6,015.00			

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 9150 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	ALUMINIUM RIM - LH <i>ut</i>	1	\$ 1,464.00	✓ 1171.20
42	ALUMINIUM RIM RUBBER VALVE - LH ?	1	\$ 5.00	? xnn
43	FRONT NO PLATE <i>nh</i>	S/N	\$ 60.00	✓
44	SUNDRIES <i>?</i> <i>nee</i>		\$ 600.00	? 17.36 ✓
TOTAL SPARE PARTS		:	\$ 25,609.00	
TOTAL LABOUR CHARGES		:	\$ 8,642.00	
GRAND TOTAL		:	\$ 34,251.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.