



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMZ 5629M

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FACE.RR.BUMPER (SN)	SCRATCHED	\$430.12	\$430.12
1	REFLECTOR ASSYL.RR (SN)	NOT NECESSARY	\$37.12	\$0.00
1	MOULDING ASSY,L.RR.BUMPER SIDE (SN)	NOT NECESSARY	\$143.85	\$0.00
1	SPACER,R.RR.BUMPER SIDE (SN)	NECESSARY	\$15.67	\$15.67
1	SPACER,L.RR.BUMPER SIDE (SN)	NECESSARY	\$15.67	\$15.67
5	CLIP.BUMPER (SN)	NECESSARY	\$8.62	\$8.62
1	PANEL COMP,REAR (SN)	NOT NECESSARY	\$398.85	\$0.00
1	BUZZER ASSYSMART (SN)	NOT NECESSARY	\$49.20	\$0.00
1	LINING COMP,L.RR.SIDE (SN)	NOT NECESSARY	\$544.35	\$0.00
1	ANTENNA ASSYL.F. (SN)	NOT NECESSARY	\$48.52	\$0.00
1	FRONT REAR SENSOR 8P (SN)	NOT NECESSARY	\$465.00	\$0.00
2	WINDSCREEN SEALANT (N) (SN)	NOT NECESSARY	\$120.00	\$0.00
1	SUNDRIES (SN)	NECESSARY	\$110.00	\$30.00
1	BODY JOINT SEALANT REAR END PANEL (SN)	NOT NECESSARY	\$120.00	\$0.00
4	SENSOR RETAINER (SN) (ADDITIONAL)	NECESSARY	\$72.00	\$72.00
			\$2,578.97	\$572.08
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)		\$250.00	\$180.00
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	NOT NECESSARY	\$250.00	\$0.00
	CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN		\$2,000.00	\$650.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)		\$2,000.00	\$520.00
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	NOT NECESSARY	\$650.00	\$0.00
	RESET VEHICLE SMART ENTRY SYSTEM	NOT NECESSARY	\$650.00	\$0.00
	REMOVE INSTALL & CALIBRATE REAR AUTO TAILGATE	NOT NECESSARY	\$650.00	\$0.00
	TO PERFORM AIMING ON MUL TI PURPOSE CAMERA FOR	NOT NECESSARY	\$650.00	\$0.00
			\$7,100.00	\$1,350.00
GRAND TOTAL			\$9,678.97	\$1,922.08



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

	RECOMMENDED COST OF REPAIRS		\$1,922.08
Report Ref No: CS/FCI24090240/Rvp3m4			

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.