



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair

Tel: +65 6841 3838

For 24-hours Roadside Assistance, Call 98203838
Website: www.honda.com.sg

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer

: MS FIRST CAPITAL INSURANCE LIMITED
#42-01116 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
: SMZ5629M
: JHMRG1880MC200727
: ODYSSEY 2.4 EX-S 21YM (EURO 6)
Owner's Name : LEE SEONG HEE
Ins Policy No. :
Date of Accident : 11/9/2024

Document No. : SQT24002489
Date : 13. Sep 2024
Customer No. : WZF002
Svc Advisor : NG SIN HAI
Engine No : K24W72540157
Date | Time : 13. Sep 2024 1:49:46 PM
Surveyor Name :
Survey Date :
Authorisation Date :
Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	9% GST Amount	Amount incld GST
TP DIRECT SETTLEMENT (JNO:)							
OWNER:							
OWNER INSURER:							
ACC DATE:							
SURVEYED BY:							
DATE:							
REF NO:							
TP INSURER:							
TP VEH:							
04715-T6A-Z00ZZ	FACE,RR,BUMPER <i>SUN</i>	1	573.50	25	430.12	38.71	468.83
33555-SLJ-013	REFLECTOR ASSYL,RR. <i>7.7.21</i>	1	49.50	25	37.12	3.34	40.46
71560-T6A-Z01	MOULDING ASSY,L,RR,BUMPER SIDE <i>7.7.21</i>	1	191.80	25	143.85	12.95	156.80
71593-T6A-Z01	SPACER,R,RR,BUMPER SIDE <i>7.7.21</i>	1	20.90	25	15.67	1.41	17.08
71598-T6A-Z01	SPACER,L,RR,BUMPER SIDE <i>7.7.21</i>	1	20.90	25	15.67	1.41	17.08
91505-TM8-003	CLIP,BUMPER <i>7.7.21</i>	5	2.30	25	1.72	0.15	1.87
66100-T6A-Q50ZZ	PANEL COMP,REAR <i>7.7.21</i>	1	531.80	25	398.85	35.90	434.75
74940-TR0-003	BUZZER ASSYSMART <i>7.7.21</i>	1	65.60	25	49.20	4.43	53.63
84665-T6A-N23ZD	LINING COMP,L,RR,SIDE <i>7.7.21</i>	1	725.80	25	544.35	48.99	593.34
38387-TZ5-A01	ANTENNA ASSYL,F. <i>7.7.21</i>	1	64.70	25	48.52	4.37	52.89
NMFRS-8P-RS886	FRONT REAR SENSOR 8P <i>7.7.21</i>	1	465.00		465.00	41.85	506.85
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>7.7.21</i>	2	60.00		120.00	10.80	130.80
Sum Item					2270.07	204.31	2,474.38
BOSUN	SUNDRIES	1	110.00		110.00	9.90	119.90
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	250.00		250.00	22.50	272.50
BOJSE	BODY JOINT SEALANT REAR END PANEL	1	120.00		120.00	10.80	130.80
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	250.00		250.00	22.50	272.50

Printed on 13/9/2024 1:55:15 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

Charges of \$50.00 (excluding GST) will be applicable for the request of quotation above \$2000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd., it will be refunded.

All quotations and prices are subjected to GST adjustment from 8% to 9% with effect from 1st Jan 2024.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: MS FIRST CAPITAL INSURANCE LIMITED	Document No.	: SQT24002489	Page	2
Registration No	: #42-0116 RAFFLES QUAY	Date	: 13. Sep 2024		
Chassis No	: HONG LEONG BUILDING	Customer No.	: WZF002		
Model	: SINGAPORE 048581	Svc Advisor	: NG SIN HAI		
Owner's Name	: SMZ5629M	Engine No	: K24W72540157		
Ins Policy No.	: JHMRC1880MC200727	Date Time	: 13. Sep 2024 1:49:46 PM		
Date of Accident	: ODYSSEY 2.4 EX-S 21YM (EURO 6)	Surveyor Name	:		
	: LEE SEONG HEE	Survey Date	:		
	: 11/9/2024	Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	9% GST Amount	Amount incld GST
BKRP02M	CUT OFF & RENEW RR PANEL, STRAIGHTEN ALIGN	1	2000.00	650	2000.00	180.00	2180.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2000.00	520	2000.00	180.00	2180.00
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	650.00	MX	650.00	58.50	708.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	650.00	MX	650.00	58.50	708.50
BC011R	REMOVE INSTALL & CALIBRATE REAR AUTO TAILGATE	1	650.00	MX	650.00	58.50	708.50
BC03R	TO PERFORM AIMING ON MULTI PURPOSE CAMERA FOR	1	650.00	MX	650.00	58.50	708.50
Sum Labor					7330.00	659.70	7989.70

Survey By Papm - Hg 9010101068

Date & Time 14/10/24

Excess 3 days

Status prg b4 pm

Signature _____

Total Amount 9,600.07 864.01 10,464.08

Total (Inclusive of GST) 10,464.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Printed on 13/09/2024 1:55:15 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

Charges of \$50.00 (excluding GST) will be applicable for the request of quotation above \$2000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 8% to 9% with effect from 1st Jan 2024.