

Date: 12-9-2024
Vehicle No: SNP1219E
Model: Toyota Sienta Hybrid
Chassis: JTDBBBA350L000159
Reg.Year: 28.10.2022

Not Authorized
Resurvey By pain
2 days
11 Sep @ 1850

Third Party Insurer: AIG
Third Party Veh No: SLG7203G
Date of Accident: 12/9/2024
Estimator: Loong
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT LH DOOR PANEL	1		<i>By</i> \$1,991.90 ✓
2	FRONT LH DOOR OUTER LOWER MOULDING	1		<i>my car</i> \$293.50 ✓
3	FRONT LH DOOR NO.1 BLACK OUT TAPE	1		<i>re</i> \$89.40 ✓
4	FRONT LH OUTER DOOR HANDLE	1		REPAIR
5	FRONT LH SIDE MIRROR	1		REPAIR
SUB TOTAL				\$2,374.80
LESS 25%				-\$593.70
PARTS TOTAL				\$1,781.10

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR INNER TRIM BOARD CLIPS	1		<i>re</i> \$50.00 X
2	FRONT DOOR OUTER MOULDING CLIPS	1		<i>re</i> \$50.00 ✓
S/N TOTAL				\$100.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT LH ACCIDENT AREAS & ETC. 200 ✓ \$300.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT LH DOOR PANEL, FRONT LH OUTER DOOR HANDLE, FRONT LH SIDE MIRROR, ETC 220 ✓ \$550.00

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS. 60 ✓ \$100.00

TO TUFF KOTE & UNDERSEAL MATERIALS. 30 ✓ \$100.00

TO CHECK WIRING & ELECTRICAL SYSTEM. 20 ✓ \$100.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

LABOUR TOTAL \$1,150.00

TOTAL \$3,031.10

Acknowledged by Repairer

Signature:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 Fax: (+65) 6481 1993

Date:

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 Fax: (+65) 6481 1011

